

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
5-Mar-24	Manggar Base	17/00 - 23.00	MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0001936-2-4 - Inspection	6	WCM-040324-SN31 ex-Tasha		DNM	
OT			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 24427-0101 - Inspection		WCM-040324-SN31 ex-Tasha			
			ADN Collar - AZIMUTHAL DENSITY DRILL COLLAR, 8-1/4 (SHRINK FIT WEAR BAND), - E4765 - Inspection		WCM_040324_LWD			
			ADN - ADN4D-CA, DRILL COLLAR ASSY, 5.75 IBS, P750 - H7749 - Inspection		WCM-070324-ADN H7749			
			IDCA - DRILL COLLAR ASSEMBLY, IMPULSE W/H.V. PORT WEAR BAND - E4821 - Inspection		WCM-070324-Impulse E4821			
			NMDC - Drill Collar, >=4.75"OD, Non-Mag, Straight - SBD-0737		dd_tools:4 March, 2024			
TOTAL (hours)				6				

* If Applicable

Mangiring, Deny, Sarwo
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

Doni Bayantoso
SLB Maintenance Supervisor