

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
26-Jan-24	Manggar Base	18.00 - 22.30	1 Set Motor A700M (Power Section) Stator - STATOR TUBE, 700OD550ID246LG THREADED - F70S0278 - Inspection ✓	4,5	A700M_07103_25Jan24		DNM	
OT ✓			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - JOP21-OSS-004 SL - Inspection		To Be Created			
			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 25287-0101 - Inspection		To Be Created			
			MWD Collar - 6.75 M10 COLLAR, INTERNAL ALIGNMENT KEY, NO R.O.P., BOX X BOX, P-550 MATERIAL - E7426 - Inspection		To Be Created			
			Control Collar (threaded) - CONTROL COLLAR 6-3/4", WITH SLEEVE STABILIZER OPTION, PD-ARCHER - N9M1154 - Ex Machine Shop		To Be Created			
			Extender - BASE, M10 UPHOLE EXTENDER - 06-042 - Inspection		MT_MEXM-06-042_240126			
				TOTAL (hours)	4,5			

* If Applicable

Mangiring, Dery, Akbar, Rifaldi, Riswan
 Personnel In Attendance

Mangiring
 ISP Inspector

 SLB Maintenance Technician

Doni Riyandoso
 SLB Maintenance Supervisor