PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Akbar, Deny, Sarwo	Customer:	PT DOWELL ANADRILL SCHLUMBERGER	Date :	
Period:	Dec-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
27-Dec-23	Manggar Base	18.00 - 22.00	String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 10 3/8_GP 7127-34 - Inspection	4	To Be Created		DNM	
OT			String Stabilizer - Stabilizer, >=6.75" OD Body, String, Steel, Integral Spiral Blade - 8 1/4_GP 7127-70 - Inspection		To Be Created			
			Control Collar - PDSC6-GA , 6-3/4"" SLEEVE-STAB. CU COLLAR, SLENDER ANCHOR BOLT HOLE - N9M1084 - Inspection		WCM_Powerdrive_28 December, 2023_SN 94701			
			Bias Unit - 8-1/2"" BIAS UNIT BODY, ORBIT 675 - 102527 - Inspection		WCM_Powerdrive_28 December, 2023_SN 94701			
			Bias Unit Ext Sub - EXTENSION COLLAR, PDX5 - 98832 - Inspection		WCM_Powerdrive_28 December, 2023_SN 94701			
			STABILIZER, UPPER, 8.375 OD, WC TILED, CRS - 4581210036-16-47 - Inspection		WCM_Powerdrive_28 December, 2023_SN 94701			
			Sonic - FLOW DIVERTER, MIDDLE 6.75 SONIC HP TOOL, EQ-S-403798 - S02140004 - Inspection		WCM_AR SonicVision_27Dec23			
			Sonic - FLOW DIVERTER, UPPER - 8.25 SONIC HP TOOL - S04110003 R - Inspection		WCM_AR SonicVision_27Dec23			
			Sonic - FLOW DIVERTER, MIDDLE 6.75 SONIC HP TOOL, EQ-S-403798 - S08130002 - Inspection		WCM_AR SonicVision_27Dec23			
			Filter Sub - Downhole Filter Screen, >=6.75"OD, Steel - Filter Screen 675-468 - Inspection		To Be Created			
			Sonic - ELECTRONIC CHASSIS, 6.75 SONIC HP TOOL - K12110214 - Inspection		WCM_AR SonicVision_27Dec23			
								EKAW A
			TOTAL (hours)	4				

* If Applicable

Mangiring, Akbar, Deny, Sarwo	Mangiring		Doni Priyantoro
Personnel In Attendance	ISP Inspector	SLB Maintenance Technician	SLB Maintenance Supervisor