

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangiring, Deny, Sarwo
 Period: Mar-23
 Day Rate:
 Per Diem Rate :


Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non:
 Rig / Well: Manggar Base

Date :
 Our Ref:


Form No. :


Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
8-Mar-24	Manggar Base	17.00 - 23.00	MSSB - MSSB-MC, CROSSOVER, 5-1/2 IF PIN X 6-5/8 FH PIN, SST - JOP20-BTS-008 SL - Ex Machine Shop	6	To Be Created		DNM	
OT			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 25379-0102 - Ex Machine Shop		To Be Created			
			X-Over - CROSSOVER SUB, M10, 6-5/8 FH BOX X 6-5/8 FH PIN - 50227 - Inspection		To Be Created			
			X-Over - XOS-NA, CROSSOVER SUB, NC-38 PIN X NC-38 PIN - SBD12809 - Inspection		To Be Created			
			VPWD - VPDA4-AA, ASSEMBLY, DRILL COLLAR, VPWD - H8441-02 - Inspection		To Be Created			
			ADN - ADN4D-BA, DRILL COLLAR ASSY, 5.75 IBS, P750 - V3163 - Inspection		WCM-070324-ADN V3163			
			UBHO - Orientating Sub, >=6.75"OD, Steel - RIB10-063-BBS - Inspection		dd_tools:5 March, 2024			
			Filter Sub - Downhole Filter Sub, >=6.75"OD, Steel - 675-468 - Inspection		S700M_FS70B0509_05Mar24			
			Torquer - LOWER TORQUER ASSEMBLY TWO PIECE TC BEARING - 21-3087 - Inspection		WCD-PDET_240309-1			
			Torquer - UPPER TORQUER ASSEMBLY 5N-m COIL 12 WAY CONNECTOR - 19-2447 - Inspection		WCD-PDET_240309-1			
			Torquer - LOWER TORQUER ASSEMBLY TWO PIECE TC BEARING - 22-4006 - Inspection		WCD-PDET_240309-1			
			Torquer - EQ-100440129 UPPER TORQUER ASSEMBLY TC BEARING 5N-M COIL - 22-5098 - Inspection		WCD-PDET_240309-1			
			Torquer - EQ-100440129 UPPER TORQUER ASSEMBLY TC BEARING 5N-M COIL - 22-4829 - Inspection		WCD-PDET_240309-1			
			Torquer - LOWER TORQUER ASSEMBLY TWO PIECE TC BEARING - 69414 - Inspection		WCD-PDET_240309-1			
				TOTAL (hours)	6			

* If Applicable


 Mangiring, Deny, Sarwo
 Personnel In Attendance


 Mangiring
 ISP Inspector


 SLB Maintenance Technician


 Deni Riyanto
 SLB Maintenance Supervisor