

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Customer: Date :
 Period: Contract/ PO Non: Our Ref:
 Day Rate: Rig / Well:
 Per Diem Rate : Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (TOOL NAME_SN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop)	BILLING				Company Representative Signature
				Hours	WO Number	BORG	Segment	
14/12/2023	CIB	17.30 - 24.00	MLWD TOOLS				D&M	
			CROSSOVER SUB SN.BKS 24850-0103 - INSPECTION					
			CROSSOVER SUB SN.BKS 25377-0103 - INSPECTION					
			CROSSOVER SUB SN.BKS 24427-0102 - INSPECTION					
			CROSSOVER SUB SN.KSBD 15140 - INSPECTION					
			LIFTING BXB SN.0330 - INSPECTION					
			MMA HOUSING SN.3490 - INSPECTION					
			ADN675 COLLAR SN.G3434 - INSPECTION					
			ARC675 COLLAR SN.52419 - INSPECTION					
			4 EA MOP SUB SN.OSS23-01236C, OSS23-01236D, OSS23-01236A, OSS23-01236B - INSPECTION					
			CROSSOVER SUB SN.JOP23-OSS-027 - INSPECTION					
			ADNM SUB SN.OSS22-00881 - INSPECTION					
			TOTAL (hours)					

[Signature]
YANUAR & HERWANTO
ISP Personnel In Attendance

[Signature]
EDIK SUHAYA
ISP Inspector

[Signature]
SLB Maintenance Technician

[Signature]
SLB Maintenance Supervisor