

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Mangiring, Sarwo, Deny, Riswan ✓
 Period: Sep-23
 Day Rate: _____
 Per Diem Rate : _____

Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non: _____
 Rig / Well: Manggar Base

Date : _____
 Our Ref: _____

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
23-Sep-23	Manggar Base	08.00 - 20:00	PD6 - PDSC6-BA, 6-3/4 LONG SLEEVE-STAB. CU COLLAR - N003569 - Ex Machine Shop	10	To Be Created		DNM	
OT		<i>break</i>	MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 23139-0103 - Ex Machine Shop		To Be Created			
		<i>time</i>	ARC - 6.75 ARC DRILL COLLAR ASSY, W/O AIM, 30K PSI - 52419 - Ex Machine Shop		To Be Created			
		<i>= 2 hrs</i>	UBHO RIB-10-0G3 - Inspection		To Be Created			
			UBHO - Orientating Sub, >=6.75"OD, steel - SBD-4961 - Inspection		To Be Created			
			UBHO - Orientating Sub, >=6.75"OD, Steel - GP-7035-40 - Inspection		To Be Created			
			Float Sub - Float Sub, >=4.75"OD, Steel - GP-6968-15LM - Inspection		DD_tools;21sept23			
			Ecoscope Collar - DV6M DRILL COLLAR - 1829 - Inspection		WCM_AR DV6MC-SS 1829_23Sep23			
TOTAL (hours)				10				<i>[Signature]</i> ERNA

* If Applicable

Mangiring, Sarwo, Deny, Riswan
 Personnel In Attendance

Mangiring
 ISP Inspector

SLB Maintenance Technician

Doni Dyantoro
 SLB Maintenance Supervisor