

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref. :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
15-Jun-24	Manggar Base	08:00-17:00	Inspected of Well Commander - 7" Well Commander with NC50 Pin x Box - B2002409A - (MPI Inspection), Ball Catcher - 7" Ball catcher with NC50 Pin x Box - B2002433A - (MPI Inspection)	8	To Be Created		MI Swaco	
TOTAL (hours)				8				

Saftiadi, Akbar, Rifaldi
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

19 JUN '24
 ON BEHALF : RIDWAN S.
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING						
				Hour/s	WO Number	BORG	Segment	Company Representative Signature		
15-Jun-24	Manggar Base	17:00-22:00	Inspected of Reamer - (RHINO XS BODY 10000 W/HVOF) - 10513718-1 - (MPI Inspection), Reamer - RHINO REAMER XS DRIVE RING 8000 - 4632766001-12-7 - (MPI Inspection), Reamer - (RHINO REAMER XS Spring Retainer 10000) - AG40171 - (MPI Inspection), Reamer - (RHINO REAMER XS PISTON 10000) - AH68841 - (MPI Inspection), Reamer - (RHINO REAMER XS DRIVE RING 10000) - AG67974 - (MPI Inspection), Reamer - (RHINO REAMER STOP RING 10000) - NN - (MPI Inspection), Reamer - Upper CAP, 10000-10375 RHINO XS2 - X18523 - (MPI Inspection), Reamer - (RHINO REAMER XS Inner Mndrel 10000) - 9AJ04766 - (MPI Inspection), Cutter Block 10000 - 5000244783-1	5	To Be Created		BDT	PT. SMITH TOOL INDONESIA		
			Inspected of Reamer XC - Lower Mandrel 10.000 - 10712766-3 - (MPI Inspection), Reamer XC - Valve Piston 8.000 - 10712191-1 - (MPI Inspection), Reamer XC - CAM Piston / Spider CAM 8.000 - 10621989-3 - (MPI Inspection), Reamer XC - CAM Mandrel 8.000 - 10712783-2 - (MPI Inspection), Reamer XC - CAM Mandrel Cap 8.000 - 10621984-1 - (MPI Inspection), Reamer XC - coupling 8.000 - 1047468-001 - (MPI Inspection), Reamer XC - Screen Sleeve 8.000 - 10622007-1 - (MPI Inspection)							
16-Jun-24	Manggar Base	08:00-17:00	Inspected of Reamer - Top Sub - 10000 - 2-9950 - (MPI Inspection), Reamer - Bottom sub - 10000 - S72453 - (MPI Inspection), Reamer XC - Cam Sub 8.000 - 2-8520 - (MPI Inspection)	8	To Be Created		BDT	PT. SMITH TOOL INDONESIA		
			Inspected of Hydra Jar - JAR - 4-3/4 OD -- 42847J						WCD_16JUN24_WCMD& SL1 JAR	BDT
			Inspected of Reamer - (RHINO XS BODY 8000 W/HVOF) -S93655 / 10544693-1						To Be Created	BDT
TOTAL (hours)				13						

Saftiadi Akbar Rifaldi
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

ON BEHALF : RIDWAN S.
 SLB Maintenance Supervisor