

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Erwin Nugraha**  
**2. Abdillah Muttaqin**  
**3. Achmad Fuad.K**

Customer: **PERTAMINA HULU MAHAKAM**


Service Date: **24 August 2020**


Periode : **August 2020**

CRO No.: **4200139209**

Rig/Well : **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TO
			18-Aug	19-Aug	20-Aug	21-Aug	22-Aug	23-Aug	24-Aug	
1	CARGO CARRYING UNIT	HCA	2	3	1	6	6	1		1
2	HYDRAULIC RAM & JACK	HCA			1					
3	SHACKLE	HCA	8	12	17	4		6		4
4	SPREADER BAR	HCA			2					
5	WIRE ROPE SLING 4 LEG	HCA	2	3		1		3	12	2
7	WIRE ROPE SLING 2 LEG	HCA						5		
8	BEAM CLAMP	HCA		12						1
9	CHAIN SLING	HCA			6					
11										
12										
13										
14										
15										
16										
17										
18										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	
4	Load Cell 30 tonnes	unit-day	0	0	0	0	1	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	
8	Meal allowance	man-day	3	3	3	3	3	3	3	2

  
**Erwin Nugraha**  
Personnel In Attendance

  
**Achmad Fuad.K**  
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Erwin Nugraha**  
**2. Abdillah Muttaqin**  
**3. Ermawan Eka Saputra**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **31 August 2020**

Periode: **August 2020**

CRO No.: **4200139209**

Rig/Well: **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TO	
			25-Aug	26-Aug	27-Aug	28-Aug	29-Aug	30-Aug	31-Aug		
1	CARGO CARRYING UNIT	HCA		6	1				2	3	
2	POLYESTER SLING	HCA			10						
3	WIRE ROPE SLING 4 LEG	HCA			3				2		
4	WIRE ROPE SLING 2 LEG	HCA									
5	WIRE ROPE SLING 1 LEG	HCA	10								
7	GIN POLE	HCA				1					
8	OVERHEAD CRANE							1			
9											
11											
12											
13											
14											
15											
16											
17											
18											
<b>Equipment Rental</b>											
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	1	0	0	
4	Load Cell 30 tonnes	unit-day	0	1	0	0	0	0	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0	
<b>PROVISION</b>											
7	Land Transportation	unit-day	1	1	1	1	1	1	1	1	
8	Meal allowance	man-day	3	3	3	3	3	3	3	3	

**Erwin Nugraha**  
Personnel In Attendance

**AHMADAN FANANI**  
Approved by PHM sites INS SPV

# PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance: **1. Erwin Nugraha**  
**2. Abdillah Muttaqin**  
**3. Achmad Fuad kaltimuja**

Customer: **PERTAMINA HULU MAHAKAM**


Service Date: **07 September 2020**

Periode: **September 2020**

CRO No.: **4200139209**

Rig/Well: **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TO
			1-Sep	2-Sep	3-Sep	4-Sep	5-Sep	6-Sep	7-Sep	
1	CARGO CARRYING UNIT	HCA	5	2			5	1	2	1
2	CARGO CARRYING UNIT INCLUDING LIFTING SET	HCA			1					
3	PAD EYE	HCA			13					1
4	SHACKLE	HCA				30		20	4	5
5	WIRE ROPE SLING 4 LEG	HCA							1	
7		HCA								
8										
9										
11										
12										
13										
14										
15										
16										
17										
18										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	
4	Load Cell 30 tonnes	unit-day	1	0	0	0	0	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	
8	Meal allowance	man-day	3	3	3	3	3	3	3	2

  
**Erwin Nugraha**

Personnel In Attendance

  
**AHMADAN FANANI**  
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Erwin Nugraha**  
**2. Abdillah Muttaqin**  
**3. Achmad Fuad Kaltimuja**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **14 September 2020**

Periode : **September 2020**

CRO No.: **4200139209**

Rig/Well : **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			8-Sep	9-Sep	10-Sep	11-Sep	12-Sep	13-Sep		14-Sep
1	CARGO CARRYING UNIT	HCA	5							5
2	CARGO CARRYING UNIT INCLUDING LIFTING SET	HCA								0
3	SHACKLE	HCA		11	2					13
4	WIRE ROPE SLING 4 LEG	HCA		2						2
5	OTHER BELOW THE HOOK LIFTING DEVICES	HCA		3						3
7	POLYESTER SLING	HCA			20					20
8	CHAIN BLOCK	HCA			2		2			4
9	LIFTING FRAME WITH PAD EYE	HCA			1					1
11	OVERHEAD CRANE	HCA						1		1
12										0
13										0
14										0
15										0
16										0
17										0
18										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	1	0	1	1	0	3
4	Load Cell 30 tonnes	unit-day	1	0	0	0	0	0	0	1
5	Wire rope tester	unit-day	0	0	0	0	0	1	0	1
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	1	0	1	1	1	6
8	Meal allowance	man-day	3	3	3	0	3	3	3	18

**Erwin Nugraha**  
Personnel In Attendance

Approved by PHM sites INS SPV