PT. INSPEKTINDO SINERGI PERSADA

SERVICES TIME SHEET

Personnel In Attendance: Mangiring,Denny,Septamon

Period: Dec-22

Day Rate:

Per Diem Rate :

Customer: Schlumberger (D&M- Well Construction)

Contract/ PO Non:

Rig / Well: Manggar Base

Date : See Below

Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY		BILLING Hour/s	WO Number	Segment	Company Representative Signature
28-Dec-22 OT	'Manggar Base	18.00 - 20.00	Performed BHA Inspection As Per DS-1 Vol #4,Tool Description As Below :					
			Bias Unit - BIAS UNIT/COLLAR ASSY FOR A 8 1/2" HOLE, PDX5 - 55311	Sn: 55311	2	WCD_28 December, 2022_PDX675_55311		
			MTA - M10 TURBINE ASSEMBLY W/FLOW DIVERTER HSG. - 4277	Sn: 4277		To Be Created		
							DNM	
				TOTAL (hours)	2			

Reviewed By:

Mangiring,Denny,Septamon
Personnel In Attendance

Doni Riyantoso
Company Representative Signature