

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YULIUS K RASDI**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **31-Aug-2021**

Periode : **Jul - Aug**

CRO No.:

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			25-Aug	26-Aug	27-Aug	28-Aug	29-Aug	30-Aug	31-Aug	
1	Pedestal Crane					IP	1			1
2										
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day					1			1
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day				1	1			2
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day				1	1			2
8	Meal allowance	man-day				2	2			4

YULIUS K

Personnel In Attendance

IWAN S / ABU KHOIRI

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YULIUS K**
USMAN K

Customer: **PERTAMINA HULU**
MAHAKAM

Service Date: **24-Aug-2021**

Periode : **Jul - Aug**

CRO No.:

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			18-Aug	19-Aug	20-Aug	21-Aug	22-Aug	23-Aug	24-Aug	
1	Pedestal Crane			IP	IP	1				1
2	Slewing Jib Davit				1					1
3	Wire Rope Sling 1-leg or 2-legs				1					1
4	Chain Block				1					1
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day			1	1				2
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day		1	1	1				3
5	Wire rope tester	unit-day			1					1
PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day		2	2	2				6

YULIUS K
Personnel In Attendance

IWAN S / ABU KHOIRI
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YULIUS K RASDI**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **7-Sep-2021**

Periode : **Jul - Aug**

CRO No.:

Rig/Well : **SMK**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			1-Sep	2-Sep	3-Sep	4-Sep	5-Sep	6-Sep	7-Sep	
1	Pedestal Crane	SMK	1							1
2	Pad Eye	SMK		5						5
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day	1							1
PROVISION										
7	Land Transportation	unit-day	1	1						2
8	Meal allowance	man-day	2	2						4

YULIUS K

Personnel In Attendance

IWAN S / ABU KHOIRI

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YULIUS K**
USMAN K

Customer: **PERTAMINA HULU**
MAHAKAM

Service Date: **31-Aug-2021**

Periode : **Jul - Aug**

CRO No.:

Rig/Well : **SMK**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			25-Aug	26-Aug	27-Aug	28-Aug	29-Aug	30-Aug	
1	Pad Eye	SMK	12	33					45
2	Shackle	SMK	8						8
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
Equipment Rental									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
PROVISION									
7	Land Transportation	unit-day		1					1
8	Meal allowance	man-day	2	2					4

YULIUS K

Personnel In Attendance

IWAN S / ABU KHOIRI

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Yulius k**
Reza Achmad

Customer: **PERTAMINA HULU**
MAHAKAM

Service Date: **14-Sep-2021**

Periode : **Sep-Oct**


CRO No.:

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			8-Sep	9-Sep	10-Sep	11-Sep	12-Sep	13-Sep	14-Sep	
1	Pedestal Crane		IP		IP	1				1
2	Cargo Carrying Unit		1							1
3	Wire Rope Sling 3-leg or 4-legs				1					1
4	Shackle				4					4
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day				1				1
PROVISION										
7	Land Transportation	unit-day	1		1	1				3
8	Meal allowance	man-day	2		2	2				6

Yulius k
Personnel In Attendance

IWAN S / ABU KHOIRI
Approved by PHM sites INS SPV

No.	TIK No.	Equipment Type	Detail Description	SWL (Ton)	LOCATION	INSPECTION DATE	PERFORMER	Color Code	Finding & Recommendation
		1							
1	TIK-4-5285	Pedestal Crane	Pedestal Crane Box Boom	10	SNB-MWPN	20-Sep-21	Yulius K	Fit For Use	1. Main hoist not acceptable red color code Winch motor main hoist leak, shall be repair. 2. Auxiliary acceptable Green color code. 3. After Repair swing lock good condition. 4. After repair swing limit switch good condition
2									
Personnel In Attendance			Meal	Equipment	Qty	Prepared by PT. ISP Inspector		Approved by PHM sites INS SPV	
1	Yulius K		1	Water bag 3 tonnes		Date : 20 September 2021		Date :	
2	Reza Ahcmad		1	Water bag 12 tonnes		 Yulius K			
3			Load Cell 5 tonnes						
TOTAL			2	Load Cell 30 tonnes					
Transport		1		Wire rope tester	1				
CRO No.						Name & Signature		Name & Signature	