

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO RASDI**

Customer: **PERTAMINA HULU MAHAKAM**


Service Date: **27-Jul-2020**

Periode : **JULY**

CRO No.: **4200139211**

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			21-Jul	22-Jul	23-Jul	SENIPAH	SENIPAH	26-Jul		27-Jul
1	PEDESTAL CRANE	PECIKO	1		1				1	3
2	CARGO CARRYING UNIT	PECIKO		1	2			1	2	6
3	SLEWING JIB DAVIT	PECIKO		1						1
4	WINCH	PECIKO		2	2					4
5	2 LEG WIRE ROPE SLING	PECIKO			2					2
6	1 LEG WIRE ROPE SLING	PECIKO	1	1	1				1	4
7	SHACKLE	PECIKO			2					2
8	4 LEG WIRE ROPE SLING	PECIKO						1		1
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
 Personnel In Attendance


IWAN S. / SETIONO
 Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**
RASDI

Customer: **PERTAMINA HULU**
MAHAKAM

Service Date: **3-Aug-2020**

Periode: **JULY - AGUSTUS**

CRO No.: **4200139211**

Rig/Well: **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty					TOTAL		
			28-Jul	29-Jul	SENIPAH	SENIPAH	SENIPAH			
1	PEDESTAL CRANE	PECIKO	1					1		
2	CARGO CARRYING UNIT	PECIKO	1	2				3		
3	SLEWING JIB DAVIT	PECIKO		1				1		
4	WINCH	PECIKO		2				2		
5	2 LEG WIRE ROPE SLING	PECIKO		1				1		
6	1 LEG WIRE ROPE SLING	PECIKO	1					1		
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	
8	Meal allowance	man-day	0	0	0	0	0	0	0	

YUDHI PRASETYO
Personnel In Attendance

IWAN S. / SETIONO
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO RASDI**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **10-Aug-2020**

Periode : **AGUSTUS**

CRO No.: **4200139211**

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			SENIPAH	SENIPAH	6-Aug	SENIPAH	SENIPAH	9-Aug	SMK	
1	PEDESTAL CRANE	PECIKO						1		1
2	CARGO CARRYING UNIT	PECIKO			2			1		3
3	SLEWING JIB DAVIT	PECIKO			1			3		4
4	WINCH	PECIKO			2					2
5	2 LEG WIRE ROPE SLING	PECIKO			1					1
6	1 LEG WIRE ROPE SLING	PECIKO			1					1
7	RUNWAY BEAM	PECIKO			1					1
8	GANTRY	PECIKO			1					
9	BEAM TROLLEY	PECIKO			1					1
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	1	0	0	0	0	1
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
 Personnel In Attendance


IWAN S. / SETIONO
 Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**
RASDI

Customer: **PERTAMINA HULU**
MAHAKAM


Service Date: **10-Aug-2020**


Periode : **AGUSTUS**

CRO No.: **4200139211**

Rig/Well : **SOUTH MAHAKAM**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			SENIPAH	SENIPAH	PECIKO	SENIPAH	SENIPAH	PECIKO	SMK	
1	PEDESTAL CRANE	SMK							1	1
2	CARGO CARRYING UNIT	SMK							1	1
3	SLEWING JIB DAVIT	SMK							1	1
4	POLYESTER SLING	SMK							2	2
5	2 LEG WIRE ROPE SLING	SMK							1	1
6	4 LEG WIRE ROPE SLING	SMK							1	1
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
Personnel In Attendance


IWAN S. / SETIONO
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **17-Aug-2020**

Periode: **AGUSTUS**

CRO No.: **4200139211**

Rig/Well: **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			SENIPAH	12-Aug	SENIPAH	14-Aug	15-Aug	16-Aug		17-Aug
1	PEDESTAL CRANE	PECIKO		2						2
2	LIFTING FRAME WITH PAD EYE	PECIKO				2				2
3	SHACKLE	PECIKO				5	4	3		12
4	SNATCH BLOCK	PECIKO				2		1		3
5	PAD EYE	PECIKO					4	4		8
6	TURNBUCKLE	PECIKO						2		2
7										0
8										
9										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO

Personnel In Attendance

IWAN S. / SETIONO

Approved by PHM sites INS SPV