

PT. INSEKTIKINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot
Period: August - September 2023
Day Rate:
Per Diem Rate:

Customer: PT. Schlumberger Indonesia - D&M
Contract/ PO Non:
Rig / Well: Duri Base

Date: 11-Sep-23
Our Ref.:


Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY (Regular)	Hours	WO Number	BILLING		Company Representative Signature
						BORG	Segment	
4-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of 2 Mud Motor (end to end), NMDC, Pommy collar, 2 String stabilizer	8	To Be Created		D&M	Anson L
5-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Mud Motor 675 power section, Mud motor 825 power section, NMDC	8	To Be Created		D&M	Anson F
6-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Mud Motor 675 power section, Mud motor 825 power section, Top sub, float sub, SPSA	8	To Be Created		D&M	Anson F
7-Sep-23	Duri Base	08.00 - 17.00	Performed inspection Mud Motor 675 1 set	8	To Be Created		D&M	Anson F
8-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Rotor, Lower rotating, shaft coupling, Upper rotating.	8	To Be Created		D&M	Anson F
				40				
				TOTAL (hours)				

* If Applicable


 Mangara, Fero
 ISF Inspector


 Anson F
 SLB Maintenance Technician


 Anson Limman
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot
 Period: August - September 2023
 Day Rate:
 Per Diem Rate:

Customer: PT Schlumberger Indonesia - D&M
 Contract/ PO Non:
 Rig / Well: Duri Base

Date: 11-Sep-23
 Our Ref:

Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY (Over Time)	BILLING			Company Representative Signature
				Hours	VO Number	Segment	
4-Sep-23	Duri Base	17.00 - 19.00	Performed inspection of string stabilizer, Bottleneck	2	To Be Created	D&M	<i>[Signature]</i>
5-Sep-23	Duri Base	17.00 - 21.00	Performed inspection of Pomy collar, 2 string stabilizer	4	To Be Created	D&M	<i>[Signature]</i>
6-Sep-23	Duri Base	17.00 - 22.00	Performed inspection of NMDC, Crossover, 2 Hole Opener, Telescope Collar.	5	To Be Created	D&M	<i>[Signature]</i>
7-Sep-23	Duri Base	17.00 - 24.00	Continue inspection of mud motor 675 1 set, Jar.	7	To Be Created	D&M	<i>[Signature]</i>
9-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Jar, Sleeves, Mud motor Power section, Telescope, NMDC, 2 String stabilizer, NMPC, Float sub, Bottleneck, Mud motor end to end	8	To Be Created	D&M	<i>[Signature]</i>
10-Sep-23	Duri Base	09.00 - 16.00	Performed inspection of Gap sub, NMPC, Jar, SPSA, NMDC	6	To Be Created	D&M	<i>[Signature]</i>
TOTAL (hours)				32			

* If Applicable

[Signature]
 Mangara, Lamhot, Fero
 Personnel In Attendance

[Signature]
 Mangara, Standuri
 ISP Inspector

[Signature]
 SLB Maintenance Technician

[Signature]
 Anson Rimmeron
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot
 Period: Agust - September 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - D&M
 Contract/ PO No: _____
 Rlg /Well: Duri Base

Date: 10-Sep-23
 Our Ref: _____

Form No. :

Billing Date	Rlg /Loc*	Time*	ACTIVITY (Regular)	BILLING'S			Company Representative Signature
				Hour/s	WO Number	Segment	
11-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Bearing section, top sub, blank sleeve	8	To Be Created	D&M	
12-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of 3 rotor, stator, bearing section, 3 top sub, 2 catcher stem, mud motor (end to end)	8	To Be Created	D&M	
13-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of 4 Bearing section, 4 stator adapter, 2 blank sleeve, 2 stator, 2 sleeve	8	To Be Created	D&M	
14-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of SPFA, pony collar, Gap sub, float sub, bottleneck	8	To Be Created	D&M	
15-Sep-23	Duri Base	08.00 - 17.00	Performed inspection of Mud motor end to end, Hole opener, bullnose, crossover	8	To Be Created	D&M	
TOTAL (hours)				40			

* If Applicable

Mangara Siantul
 ISF Inspector

Mangara Lamhot Fero
 Personnel in Attendance

SLB Maintenance Supervisor

SLB Maintenance Technician



PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Date : 18-Sep-23
Our Ref. :

Customer : PT. Schlumberger Indonesia - D&M
Contract/ PO Non :
Rig / Well : Duri Base

Personnel In Attendance: Mangara, Fero, Lambot
Period: August - September 2023
Day Rate:
Per Diem Rate :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Over Time)	BILLING				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
13-Sep-23	Duri Base	17.00 - 22.00	Performed inspection of Bottleneck, Crossover, string stabilizer, mud motor end to end, pony collar, jar.	5	To Be Created		D&M	
14-Sep-23	Duri Base	17.00 - 22.00	Performed inspection of 2 NMDC, Mud motor end to end	5	To Be Created		D&M	
16-Sep-23	Duri Base	08.00 - 22.00	Performed inspection of 2 stator, 2 rotor, adjusting ring, catcher stem, splined mandrel, 2 string stabilizer. Cleaning Mud motor 1 set, bottleneck and float sub.	13	To Be Created		D&M	
17-Sep-23	Duri Base	08.00 - 17.00	Continue inspection of mud motor 1 set, bottleneck and float sub. Performed inspection of 2 pony collar, jar, telescope, SP&A, NMDC.	8	To Be Created		D&M	
TOTAL (hours)				31				

* If Applicable

Manuara, Sianturi
ISP Inspector

Manuara, Sianturi
ISP Inspector

Manuara, Sianturi
SLB Maintenance Technician

Manuara, Sianturi
SLB Maintenance Supervisor

PT. INSEKTINGDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Faro, Lamhot
 Period: August - September 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT Schlumberger Indonesia - D&M
 Contract/ PO Non: _____
 Rig / Well: Duri Base

Date: 21-Sep-23
 Our Ref: _____
 Form No. : _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (Over Time)	BILLING			Company Representative Signature
				Hours	WO Number	BORG Segment	
18-Sep-23	Duri Base	17.00 - 21.00	Cleaning mud motor power section	4	To Be Created	D&M	
19-Sep-23	Duri Base	17.00 - 20.00	Cleaning 2 NIMDC, Gap sub, String stabilizer, crossover, Pony collar.	3	To Be Created	D&M	
20-Sep-23	Duri Base	17.00 - 21.00	Performed inspection of 2 mud motor end to end. Performed visual inspection of 4 top sub, 4 sleeve, 4 catcher stem.	4	To Be Created	D&M	
TOTAL (hours)				11			

* If Applicable

Mangara, Lamhot, Faro
Personnel In Attendance

Mangara, Siaulud
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

