

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:   
 Period:   
 Day Rate:   
 Per Diem Rate :

Customer:   
 Contract/ PO Non:   
 Rig / Well:

Date :   
 Our Ref:   
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Over Time)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
7-Aug-23	Duri Base	17.00 - 18.00	Performed Inspection 2 Mud motor end to end, SPSA, Saver sub, Float sub, NMPC, 2 Crossover	1	To Be Created		D&M	
8-Aug-23	Duri Base	17.00 - 20.00	Performed Inspection Mud motor 675 1 set	3	To Be Created		D&M	
10-Aug-23	Duri Base	17.00 - 21.00	Performed Inspection of 7 Stator, 2 Blind sleeve, 2 NMDC	4	To Be Created		D&M	
12-Aug-23	Duri Base	14.00 - 23.00	Performed Inspection of 4 stator and cleaning 10 sub part of mud motor	9	To Be Created		D&M	
13-Aug-23	Duri Base	08.00 -20.00	Performed Inspection of Crossover Bottleneck, 24 sub part of mud motor	11	To Be Created		D&M	
<b>TOTAL (hours)</b>				<b>28</b>				

\* If Applicable

  
  
 Mangara, Lamhot, Fero  
 Personnel In Attendance

  
  
 Mangara Sianturi  
 ISP Inspector

\_\_\_\_\_  
 SLB Maintenance Technician

\_\_\_\_\_  
 SLB Maintenance Supervisor