

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: M. FHADLY & BOBI M.
 Period: _____
 Day Rate: _____
 Per Diem Rate : _____

Customer: PT. Solusi Bangun Indonesia
 Contract/ PO Non: _____
 Rig / Well: Cilacap Plant.

Date : 14 Jan 2022
 Our Ref: _____

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	Kamis, 23-12-2021	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, NDT Hook & Perform load testing.	1		
2	Jumat, 24-12-2021	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, NDT Hook & Prepare for load test.	1		
3	Sabtu 25-12-2021	Cilacap	OFF		-		
4	Minggu, 26-12-2021	Cilacap	OFF		-		
5	Senin, 27-12-2021	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, NDT Hook & Perform Load testing	1		
6	Selasa, 28-12-2021	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, NDT Hook & Preparation for load testing	1		
7	Rabu 29-12-2021	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, NDT Hook & Perform load testing.	1		
TOTAL (Days)					5		
TOTAL (USD)							
GRAND TOTAL							

* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark
	Kamis, 23-12-2021	NDT Chemical (SM-15 & MP-35)	7 Lt.	Consumable
		Paint Remover	1 ea.	Consumable.
		LOAD Cell 55 ton.	1 ea.	tools.
		Round Ring 20 ton x 12 meter.	2 ea.	TOOLS
		Shackle 55 ton = 2 ea Shackle 35 ton = 3 ea. Shackle 17 ton = 2 ea.		TOOLS.
	Rabu, 29-12-2021	Shackle 8.5 ton = 7 ea. Master link = 1 ea.		

M. Fhadly
 Personnel In Attendance

 Contractor Representative

[Signature]
 The Company Representative

PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance: M. F. HADLY & BOBI M.
 Period: _____
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Solusi Bangun Indonesia
 Contract/ PO Non: _____
 Rig / Well: Cilacap Plant

Date: 14 Jan 2022
 Our Ref: _____

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	Kamis, 06-01-2022	Cilacap	07 ³⁰ -16 ⁰⁰	Continue inspect Hurst After Repair	1		
2	Jumat, 07-01-2022	Cilacap	07 ³⁰ -16 ⁰⁰	Continue inspect Hurst After Repair.	1		
3	Sabtu, 08-01-2022	Cilacap	OFF	OFF	-		
4	Minggu, 09-01-2022	Cilacap	OFF	OFF	-		
5	Kamis, 10-01-2022	Cilacap	07 ³⁰ -16 ⁰⁰	Function test Hurst After Repair	1		
6	Juma, 11-01-2022	Cilacap	07 ³⁰ -16 ⁰⁰	Function test Hurst After Repair, Load test (Fail)	1		
7	Rabu, 12-01-2022	Cilacap	07 ³⁰ -16 ⁰⁰	Visual check, MDT Spreader Bar & preparation for load test	1		
TOTAL (Days)					5		
TOTAL (USD)							
GRAND TOTAL							

* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark
	Kamis, 06-01-2022	MDT Chemical (SM-15 & MP 35)	7 Lt.	Consumable
		Paint remover	7 ea.	Consumable
		Load Cell 55 ton	1 ea.	tools
		Round Ring 20 ton x 12 m	2 ea.	tools
		Shackle 50 ton = 2 ea Shackle 35 ton = 3 ea Shackle 17 ton = 2 ea.		tools
	Rabu, 12-01-2022	Shackle 0.5 ton = 7 ea. Master link = 1 ea.		

M. F. Hadly
 Personnel In Attendance

Contractor Representative

[Signature]
 The Company Representative

