PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Bernard & Team	Customer:	PETRONAS	Date :	17-Dec-21
Period:	01 to 17 /12/21	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Petronas (Lamongan Shore Base)		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
01/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
02/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
03/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
04/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
05/12/2021	LSB	08.00-17.00	Inspection Tubing, 5 1/2" OD,17 PPF, L-80, TSH BLUE , R-3	1		
06/12/2021	LSB	08.00-17.00	Inspection Tubing, 5 1/2" OD,17 PPF, L-80, TSH BLUE , R-3	1		
07/12/2021	LSB	08.00-17.00	Inspection Tubing, 5 1/2" OD,17 PPF, L-80, TSH BLUE , R-3	1		
08/12/2021	LSB	08.00-17.00	Inspection Tubing, 5 1/2" OD,17 PPF, L-80, TSH BLUE , R-3	1		
10/12/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD,9.2 PPF, L-80, VAM TOP , R-2	1		
11/12/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD,9.2 PPF, L-80, VAM TOP , R-2	1		
12/12/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD,9.2 PPF, L-80, VAM TOP , R-2	1		
13/12/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD,9.2 PPF, L-80, VAM TOP , R-2	1		
14/12/2021	LSB	08.00-17.00	Inspection Various Pup Joint	1		
15/12/2021	LSB	08.00-17.00	Inspection Various Pup Joint	1		
16/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
17/12/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TSH ER CONNECTION, R-3	1		
			GRAND TOTAL			

* If Applicable

PT. INSPEKTINDO SINERGI PERSADA

Personnel In Attendance

Contractor Representative

Rig Representative

KUTAPANG IT LTD

The Company Representative

Scanned by TapScanner