

# PT. INSPEKTINDO SINERGI PERSADA

## SERVICES TIME SHEET



Personnel In Attendance:

1.Idham , 2. Reza Kukuh, 3. Septamon 4. Andik Kurniawan, 5.Rifaldi Arif, 6.Albert Owen, 7. Lefi Hotmatua, 8.Iskandar, 9.Siti Fatimah, 10. Novela Ferista

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Aug-22

Period:

JULY-AUG 2022

Contract/ PO Non:

471000000

Our Ref:

Service Date:

21 July - 20 August 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
21-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
22-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
23-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
24-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
25-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
26-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
27-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
28-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
29-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
30-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 20"	4300071106	1	1
31-Jul-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
01-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
02-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
03-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
04-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
05-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
06-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
07-Aug-22	Bunyu Field		OFF			
08-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
09-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
10-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
11-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
12-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
13-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
14-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
15-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
16-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
17-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
18-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

1. Idham, 2. Reza Kukuh, 3. Septamon, 4. Andik Kurniawan, 5. Rifaldi Arif, 6. Albert Owen, 7. Lefi Hotmatua, 8. Iskandar, 9. Siti Fatimah, 10. Novela Ferista

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Aug-22

Period:

JULY-AUG 2022

Contract/ PO Non:

4710000000

Our Ref:

Service Date:

21 July - 20 August 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
19-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
20-Aug-22	Bunyu Field	07.00 - 16.00	Set Up Location and tools, Pipe Yard Management & Inspection Casing 9-5/8"	4300071106	1	1
TOTAL (Days)					30	30

**Chasan Musthopa / Idham**  
Personnel In Attendance

Field Site Representative

**Akbar Bayu Ardianto**  
The Company Representative

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: 1. Pambudhy K, 2. Septamon, 3. Rifaldi, 4. Chasan, 5. Dhony, 6. Roberto, 7. Marselinus, 8. Musa, 9. Andik Kurniawan, 10. Idham

Customer: PT Pertamina EP

Date: 20-Aug-22

Period: August 2022

Contract/ PO Non: 471000000/09.06.2022

Date :

Our Ref:

Period:

Day Rate:

Rig / Well:

Pertamina EP Asset 5 - Tarakan Field

Per Diem Rate :

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	Monday, 1 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 50 joints of Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949.	1		
2	Tuesday, 2 Agustus 2022	Tarakan Field	07.00-16.00	Assist Loading and Loading Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949	1		
3	Wednesday, 3 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 53 joints of Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949.	1		
4	Thursday, 4 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 34 joints of Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949.	1		
5	Friday, 5 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 16 joints of Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949.	1		
6	Saturday, 6 Agustus 2022	Tarakan Field	07.00-16.00	Assist Loading and Loading Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949	1		
7	Sunday, 7 Agustus 2022	Tarakan Field	07.00-16.00	Assist Loading Casing 9-5/8" OD and Casing 13-3/8" OD for inspection.	1		
8	Monday, 8 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 40 joints of Casing 7" OD, 26 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 6,151", RO No: 4300071949.	1		
9	Tuesday, 9 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 30 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,679", RO No: 4300071949.	1		
10	Wednesday, 10 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 25 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,679", RO No: 4300071949.	1		
11	Thursday, 11 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 20 joints of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12,456", RO No: 4300072035.	1		
12	Friday, 12 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 15 joints of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12,456", RO No: 4300072035.	1		
13	Saturday, 13 Agustus 2022	Tarakan Field	07.00-16.00	Waiting Lifting Operational and Preparation Tools	1		
14	Sunday, 14 Agustus 2022	Tarakan Field	07.00-16.00	Waiting Lifting Operational and Preparation Tools	1		
15	Monday, 15 Agustus 2022	Tarakan Field	07.00-16.00	Waiting Lifting Operational and Preparation Tools	1		
16	Tuesday, 16 Agustus 2022	Tarakan Field	07.00-16.00	Waiting Lifting Operational and Preparation Tools	1		
17	Wednesday, 17 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 20 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,599", RO No: 4300053121 ex Stock	1		
18	Thursday, 18 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 20 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,599", RO No: 4300053121 ex Stock	1		
19	Friday, 19 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 20 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,599", RO No: 4300053121 ex Stock	1		
20	Saturday, 20 Agustus 2022	Tarakan Field	07.00-16.00	Inspection 20 joints of Casing 9-5/8" OD, 40 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 8,599", RO No: 4300053121 ex Stock	1		
<b>TOTAL (Days)</b>					20		
<b>TOTAL (USD)</b>							
<b>GRAND TOTAL</b>							

\* If Applicable

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



1. Pambudhy K. 2. Septamon. 3. Rifaldi. 4. Chasan. 5. Dhony. 6. Roberto. 7. Marselinus. 8. Musa. 9. Andik Kurniawan. 10. Idham

PT Pertamina EP

20-Aug-22

August 2022

4710000000/09.06.2022

Pertamina EP Asset 5 - Tarakan Field

Personnel In Attendance:

Period:

Day Rate:

Per Diem Rate:

Customer:

Contract/ PO Non:

Rig / Well:

Date :

Our Ref:

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
<b>Consumable Material Usage</b>							
No	Date & Day	Material Usage			Quantity	Remark	

*Chasan Musthopa*  
Chasan Musthopa/Idham  
Personnel In Attendance

*Dhony T. B.*  
Dhony T. B.  
Contractor Representative

\_\_\_\_\_  
Rig Representative

\_\_\_\_\_  
The Company Representative