

PT. INSPEKTING SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

1.Chasan, 2. Albert, 3. Levi, 4. Iskandar, 5. Swargi, 6 Andik K. 7. Reza K. 8.Berto, 9.Marchel, 10.Musa 11.Idham

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Nov-22

Period:

November 2022

Contract/ PO Non:

4710000000

Our Ref:

Service Date:

21 October - 20 November 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
21-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO Number: 4300072035	1	1
22-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO Number: 4300072035	1	1
23-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO Number: 4300072035	1	1
24-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
25-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
26-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
27-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
28-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
29-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
30-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
31-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
1-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
2-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
3-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Tubing 3 1/2" OD, 9.3 PPF, N-80, EUE, Length R-2, API Drift 2.867".	RO Number: 4300056110	1	1
4-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
5-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
6-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
7-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
8-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number: 4300071106	1	1
9-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151". CASING 9-5/8", 40 PPF, N-80Q, BUTTRESS CONN PIN X BOX, LENGTH R3, API DRIFT 8.679"	RO Number: 4300071106 RO Number: 4300072669	1	1
10-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1

PT. INSPEKTOR SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:	1.Chasan, 2. Albert, 3. Levi, 4. Iskandar, 5. Swargi, 6 Andik K. 7. Reza K. 8.Berto, 9.Marchel, 10.Musa 11.Idham	Customer:	Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field	Date :	20-Nov-22
Period:	November 2022	Contract/ PO Non:	4710000000	Our Ref:	
Service Date:	21 October - 20 November 2022	Rig / Well:	Bunyu Well		

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
11-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
12-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
13-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151". CASING 20" ERW, 94 PPF, K-55, BUTTRESS CONN PIN X BOX, LENGTH R3, API DRIFT 18.936"	RO Number 4300072669	1	1
14-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
15-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
16-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
17-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
18-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
19-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669	1	1
20-Nov-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of 7" OD, 26 PPF, N-80, Btc Pin X Box, Length R-3, API Drift 6.151".	RO Number 4300072669		
TOTAL (Days)					30	30

Chasan Musthopa / Idham
Personnel In Attendance

Field Site Representative

Ardi Septiawan

The Company Representative