

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1. Erwin Nugraha**
2. Abdillah Muttaqin
3. Achmad Fuad.K

Customer: **PERTAMINA HULU MAHAKAM**


Service Date: **24 August 2020**


Periode : **August 2020**

CRO No.: **4200139209**

Rig/Well : **HANDIL BASE**


No.	Service Description	Rig/Loc	Date of Inspection & Qty							TO
			18-Aug	19-Aug	20-Aug	21-Aug	22-Aug	23-Aug	24-Aug	
1	CARGO CARRYING UNIT	HCA	2	3	1	6	6	1		1
2	HYDRAULIC RAM & JACK	HCA			1					
3	SHACKLE	HCA	8	12	17	4		6		4
4	SPREADER BAR	HCA			2					
5	WIRE ROPE SLING 4 LEG	HCA	2	3		1		3	12	2
7	WIRE ROPE SLING 2 LEG	HCA						5		
8	BEAM CLAMP	HCA		12						1
9	CHAIN SLING	HCA			6					
11										
12										
13										
14										
15										
16										
17										
18										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	
4	Load Cell 30 tonnes	unit-day	0	0	0	0	1	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	
PROVISION										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	
8	Meal allowance	man-day	3	3	3	3	3	3	3	2


Erwin Nugraha
Personnel In Attendance


Achmad Fuad.K
Approved by PHM sites INS SPV

SUMMARY LIFTING EQUIPMENTS INSPECTION CAMPAIGN 2nd SEMESTER 2020

SITE : HANDIL BASE (HCA)

No.	TIK No.	Equipment Type	Description	SWL (Ton)	LOCATION	INSPECTION DATE	PERFORMER	Color Code	Finding & Recommendation	
		3								
1	TIK-9469-0	Cargo Carrying unit	Skid Basket	10	HCA-Material Dispatcher	31/08/2020	ISP-Erwin Nugraha	SERVICEABLE	Safety marking along perimeter rail was found blurred,Should be repainted with contrasting color.Previuse not found last color code solid green. Last load test was 30/5/2020.	
2	TIK-8493-0	Cargo Carrying unit	Skid Basket	10	HCA-Material Dispatcher	31/08/2020	ISP-Erwin Nugraha	SERVICEABLE	Safety marking along perimeter rail was found blurred,Should be repainted with contrasting color.Previuse not found last color code solid green. Last load test was 30/5/2020.	
3	TIK-10835-0	Cargo Carrying unit	Burnable waste Basket	2	HCA-Material Dispatcher	31/08/2020	ISP-Erwin Nugraha	SERVICEABLE	Frame top and bottom found scratced,shall be clean up and repainting.Lifting set is not available,to be provided	
Personnel In Attendance		Meal		Equipment	Qty	Prepared by PT. ISP Inspector		Approved by PHM sites INS SPV		
1	Erwin Nugraha	1		Water bag 3 tonnes		Date :	31 August 2020		Date :	August 2020
2	Abdillah Muttaqin	1		Water bag 12 tonnes		 Erwin Nugraha				
3	Ahmad Fuad kaltimuja	1		Load Cell 5 tonnes						
TOTAL		3		Load Cell 30 tonnes						
Transport	1		Wire rope tester							
CRO No.	4200139209						Name & Signature		Name & Signature	

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1. Erwin Nugraha**
2. Abdillah Muttaqin
3. Achmad Fuad kaltimuja

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **07 September 2020**

Periode: **September 2020**

CRO No.: **4200139209**

Rig/Well: **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TO
			1-Sep	2-Sep	3-Sep	4-Sep	5-Sep	6-Sep	7-Sep	
1	CARGO CARRYING UNIT	HCA	5	2			5	1	2	1
2	CARGO CARRYING UNIT INCLUDING LIFTING SET	HCA			1					
3	PAD EYE	HCA			13					1
4	SHACKLE	HCA				30		20	4	5
5	WIRE ROPE SLING 4 LEG	HCA							1	
7		HCA								
8										
9										
11										
12										
13										
14										
15										
16										
17										
18										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	
4	Load Cell 30 tonnes	unit-day	1	0	0	0	0	0	0	
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	
PROVISION										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	
8	Meal allowance	man-day	3	3	3	3	3	3	3	2

Erwin Nugraha

Personnel In Attendance

AHMADAN FANANI
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1. Erwin Nugraha**
2. Abdillah Muttaqin
3. Achmad Fuad Kaltimuja

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **14 September 2020**

Periode : **September 2020**

CRO No.: **4200139209**

Rig/Well : **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			8-Sep	9-Sep	10-Sep	11-Sep	12-Sep	13-Sep		14-Sep
1	CARGO CARRYING UNIT	HCA	5							5
2	CARGO CARRYING UNIT INCLUDING LIFTING SET	HCA								0
3	SHACKLE	HCA		11	2					13
4	WIRE ROPE SLING 4 LEG	HCA		2						2
5	OTHER BELOW THE HOOK LIFTING DEVICES	HCA		3						3
7	POLYESTER SLING	HCA			20					20
8	CHAIN BLOCK	HCA			2		2			4
9	LIFTING FRAME WITH PAD EYE	HCA			1					1
11	OVERHEAD CRANE	HCA						1		1
12										0
13										0
14										0
15										0
16										0
17										0
18										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	1	0	1	1	0	3
4	Load Cell 30 tonnes	unit-day	1	0	0	0	0	0	0	1
5	Wire rope tester	unit-day	0	0	0	0	0	1	0	1
PROVISION										
7	Land Transportation	unit-day	1	1	1	0	1	1	1	6
8	Meal allowance	man-day	3	3	3	0	3	3	3	18

Erwin Nugraha
Personnel In Attendance

Approved by PHM sites INS SPV

