

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Gunawan R.**  
**Abdillah M.**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **November 25, 2020**

Periode : **November**

CRO No.: **8532781**

Rig/Well : **PHM - BEKAPAI**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			19-Nov	20-Nov	21-Nov	22-Nov	23-Nov	24-Nov	25-Nov	
1	Gantry		1							1
2	Cargo Carrying Unit		1	2		3	1	1		8
3	Runway Beam		1	1		1	1	2		6
4	Slewing Jib Davit			1			1		1	3
5	Powered Hoist			1						1
6	Beam Trolley			1						1
7	Lifting Frame With Pad Eye				10					10
8	Plate Handling Clamp				1		1			2
9	Hydraulic Ram & Jack				1				1	2
10	Wire Rope Sling 1-leg or 2-legs				3				5	8
11	Polyester Sling						4		3	7
12	Shackle							6	9	15
13	Wire Rope Sling 3-leg or 4-legs							1	2	3
14	er Below The Hook Lifting Dev								1	1
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
<b>PROVISION</b>										
7	Land Transportation	unit-day	1							1
8	Meal allowance	man-day								

**GUNAWAN R.**  
 Personnel In Attendance

**BUKTI H. / JOKO S.**  
 Approved by PHM sites INS SPV