

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:	Chasan Musthopa, Imansyah S, Khabib S, M Choiri, A Safaul, A Muttadin	Customer:	PETRONAS	Date:	20-Mar-22
Period:	17 to 20 March 2022	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Lamongan Shorebase	Form No.:	
Per Diem Rate:					

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
17-Mar-22	Lamongan Shorebase	08.00 - 17.00	Preparation Equipment Tools, Consumable at Petronas Yard and Housekeeping.	1		
18-Mar-22	Lamongan Shorebase	08.00 - 17.00	Waiting Loading Pipe and Preparation Equipment Tools, Consumable House keeping at Petronas Yard.	1		
19-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection 4 joints Casing 13-3/8 inch OD, 68 PPF, L-80, DWC/C, R-3, : Open/Closed Protector, Internal / External Cleaning, VTI, VBI, FLD, Internal Coating, Apply Thread Compound, Close Protector. SAP 51069632	1		
			Inspection 1 joint Casing 13-3/8 inch OD, 68 PPF, L-80, DWC/C, R-3, c/w Reamer shoe, : Open/Closed Protector, Internal / External Cleaning, VTI, VBI, FLD, Internal Coating, Apply Thread Compound, Close Protector. SAP NON STOCK			
			Inspection and 9 joints Casing 13-3/8 inch OD, 68 PPF, L-80, BTC, R-3, : Open/Closed Protector, Internal / External Cleaning, VTI, VBI, FLD, Internal Coating, Apply Thread Compound, Close Protector. SAP 50569927			
			Inspection 1 joint Casing 13-3/8 inch OD, 68 PPF, L-80, BTC, R-3, c/w Reamer shoe : Open/Closed Protector, Internal / External Cleaning, VTI, VBI, FLD, Internal Coating, Apply Thread Compound, Close Protector. SAP 50569927			
20-Mar-22	Lamongan Shorebase	08.00 - 17.00	Continue Inspection 4 joints Casing 13-3/8 inch OD, 68 PPF, L-80, DWC/C, R-3, : External Cleaning and Coating. SAP 51069632	1		
			Continue Inspection 1 joint Casing 13-3/8 inch OD, 68 PPF, L-80, DWC/C, R-3, c/w Reamer shoe. : External Cleaning and Coating, SAP NON STOCK			
			Continue Inspection 9 joints Casing 13-3/8 Inch OD, 68 PPF, L-80, BTC, R-3, : External Cleaning and Coating. SAP 50569927			
			Continue Inspection 1 joint Casing 13-3/8 inch OD, 68 PPF, L-80, BTC, R-3, c/w Reamer shoe : External Cleaning and Coating. SAP 50569927			
			Continue Inspection 1 joint Casing 13-3/8 inch OD, 68 PPF, L-80, BTC, R-3, c/w Float Collar : External Cleaning and Coating. SAP 50569927			
				TOTAL (Days)	4	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Chasan Musthopa
Chasan Musthopa
Personnel In Attendance

Contractor Representative

Rig Representative

[Signature]
The Company Representative

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:	Chasan Musthopa, Imansyah S, Khabib S, M Cholri, A Safaul, A Muttadin	Customer:	PETRONAS	Date:	27-Mar-22
Period:	21 to 27 March 2022	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Lamongan Shorebase	Form No.:	
Per Diem Rate:					

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
21-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection 24 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. 1 joint Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. c/w Float Collar. Open/Close Protector, Cleaning Connection, VLD, VTI, VBI, UTG, Aply Thread Compound. SAP NON STOCK	1		
22-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection 15 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. Open/Close Protector, Cleaning Connection, Internal Cleaning, FLD, VTI, FLVBI, UTG, Aply Thread Compound. SAP 51070764	1		
23-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection 15 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. External Coating. SAP 51070764	1		
24-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. Open/Close Protector, Cleaning Connection, Internal Cleaning, VLD, VTI, VBI, UTG, Aply Thread Compound. SAP 51070764	1		
25-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and maintenance of 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. External Cleaning Body. SAP 51070764.	1		
26-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and maintenance of 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. External Coating and Marking. SAP 51070764.	1		
27-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and maintenance of 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. Open/Close Protector, Cleaning Connection, Internal Cleaning, VLD, VTI, VBI, UTG, Aply Thread Compound, External Cleaning and Coating SAP 51070764	1		
				TOTAL (Days)	7	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Mu/19
Chasan Musthopa
Personnel In Attendance

Contractor Representative

Rig Representative

[Signature]
The Company Representative *[Signature]*



PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:	Chasan Musthopa, Imansyah S, Khabib S, M Choiri, A Safaul, A Muttadin	Customer:	PETRONAS	Date:	3-Apr-22
Period:	28 March To 3 April 2022	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Lamongan Shorebase	Form No.:	
Per Diem Rate:					

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mobi/ Diemb (USD)	Per diem (Day)
28-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and maintenance of 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. External Cleaning and Coating SAP 51070764	1		
29-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and maintenance of 30 joints Casing 9-5/8 inch OD, 47 PPF, L-80, VAM 21 HT, R-3. Colour Code and Marking SAP 51070764 , Waiting for Loading UnLoading Pipe.	1		
30-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 23 joints Casing 18-5/8"OD, 87.5 ppf, K-55, TSH ER, R 3. Open Protector, Cleaning Connection, Internal Cleaning, FLD, VTI,UTG, Apply Thread Compound, Close Protector. SAP: 51072405	1		
31-Mar-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance Casing 18-5/8"OD, 87.5 ppf, K-55, TSH ER, R 3. External Cleaning and Coating. SAP: 51072405	1		
1-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance Casing 18-5/8"OD, 87.5 ppf, K-55, TSH ER, R 3. Internal and External Cleaning and Coating. SAP: 51072405	1		
2-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 23 joints Casing 18-5/8"OD, 87.5 ppf, K-55, TSH ER, R 3. Colour Code and Marking. SAP: 51072405 . Waiting Loading UnLoading.	1		
3-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 30 joints Casing perforated 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. Open Protector, Cleaning Connection, Internal Cleaning, FLD, VTI. SAP: 51070927 .	1		
				TOTAL (Days)	7	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Musthopa
Chasan Musthopa
Personnel In Attendance

Contractor Representative

Rig Representative

The Company Representative

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Chasan Musthopa, Imansyah S,
Khabib S, M Choiri, A Safaul, A
Muttadin

Customer:

PETRONAS

Date:

10-Apr-22

Period:

4 To 10 April 2022

Contract/ PO Non:

Our Ref:

Day Rate:

Rig / Well:

Lamongan Shorebase

Per Diem Rate :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
4-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 10 joints Casing 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. SAP: 51069663. 1 joint SPACER NIPPLE 5-1/2" OD, 17ppf, PSL 2, L-80, VAM TOP, R-3. SAP : 51068573. Open Protector, Cleaning Connection, Internal Cleaning, FLD, VTI and 41 joints External Cleaning.	1		
5-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance Casing 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. 30 joints. SAP: 51070927. 10 joints SAP: 51069663. 1 joint SAP : 51068573. Apply Thread Compound, Close Protector, and 41 joints External Coating.	1		
6-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance Casing 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. 30 joints. SAP: 51070927. 10 joints SAP: 51069663. 1 joint SAP : 51068573. Apply Colour Code and Marking. Inspection And Maintenance 66 joints Tubing 3-1/2"OD, 9.2ppf, L-80, VAM TOP, R-2. SAP 51069664. Open Protector, Cleaning Connection, FLD, FLBI, VTI, UTG, Internal Cleaning. Apply Thread Compound, Close Protector.	1		
7-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection And Maintenance 66 joints Tubing 3-1/2"OD, 9.2ppf, L-80, VAM TOP, R-2. SAP 51069664. External Cleaning and Coating.	1		
8-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection And Maintenance 66 joints Tubing 3-1/2"OD, 9.2ppf, L-80, VAM TOP, R-2. SAP 51069664. Colour Code and Marking. 16 jts Pup Joint 5-1/2"OD, 17ppf, L-80, VAM TOP, 6ft. SAP 51069671. 15 jts Pup Joint 5-1/2"OD, 17ppf, L-80, VAM TOP, 10ft. SAP 51069672	1		
9-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection And Maintenance, 16 jts Pup Joint 5-1/2"OD, 17ppf, L-80, VAM TOP, 6ft. SAP 51069671. 15 jts Pup Joint 5-1/2"OD, 17ppf, L-80, VAM TOP, 10ft. SAP 51069672. 3 jts Pup Joint 4-1/2"OD, 12.6ppf, L-80, VAM TOP, Various Length. SAP NON STOCK	1		
10-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection And Maintenance 7 joints Casing 18-5/8"OD, 87.5ppf, L-80, TP-QR, R-3. SAP 51071508. Cleaning Connection, FLD, FLVBI, UTG, VTI, External Cleaning and Coating.	1		
				TOTAL (Days)	7	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Chasan Musthopa
Chasan Musthopa
Personnel In Attendance

Contractor Representative

Rig Representative

Taufiq Hidayat
The Company Representative

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:

Chasan Musthopa, Imansyah S,
Khabib S, M Cholri, A Safaul, A
MuttadIn

Customer:

PETRONAS

Date :

20-Apr-22

Period:

11 To 20 April 2022

Contract/ PO Non:

Our Ref:

Day Rate:

Rig / Well:

Lamongan Shorebase

Per Diem Rate :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
11-Apr-22	Lamongan Shorebase	08.00 - 17.00	Waiting Loading / UnLoading and House keeping Inspection Area.	1		
12-Apr-22	Lamongan Shorebase	08.00 - 17.00	Waiting Loading / UnLoading and House keeping Inspection Area.	1		
13-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance of 18 joints Casing 13-3/8"OD, 68 ppf, P-110, BTC, R 3. SAP: 50650338. 6 joints Tubing 4-1/2"OD, 12.6ppf, L-80, VAM TOP, R3. SAP 51069675. 2 joints Casing 13-3/8"OD, 87.5ppf, K-55, TP-QR, R3. SAP 51071508. Open Protector, Cleaning Connection,FLD,FLBI,VTI,UTG,Internal Cleaning, Apply Thread Compound,Close Protector.	1		
14-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance of 18 joints Casing 13-3/8"OD, 68 ppf, P-110, BTC, R 3. SAP: 50650338. External Cleaning and Coating.	1		
15-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection And Maintenance of 4 joints Pup Joint 4-1/2"OD, 12.6ppf, L-80,VAM TOP, 6ft, NON STOCK. 6 joints Pup Joint 4-1/2"OD, 12.6ppf, L-80,VAM TOP, 10ft, NON STOCK. 1 joint Pup joint 18-5/8"OD, 87.5ppf, K-55, TP-QR, 15ft.SAP Open Protector, Cleaning Connection,FLD,FLBI,VTI,UTG,Internal Cleaning, Apply Thread Compound,Close Protector.6 joints Tubing 4-1/2"OD,12.6ppf, L-80, VAM TOP, R3. SAP 51069675. 2 joints Casing 13-3/8"OD, 87.5ppf, K-55, TP-QR, R3. SAP 51071508. External Cleaning and Coating.	1		
16-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 39 joints Casing Liner PDRL 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. Open Protector, Cleaning Connection, Internal Cleaning, FLD, VTI. SAP: 51070927.	1		
17-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 39 joints Casing Liner PDRL 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. Internal Cleaning and External Cleaning / coating. SAP: 51070927.	1		
18-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 39 joints Casing Liner PDRL 5-1/2"OD, 17 ppf, L-80, VAM TOP, R 3. Colour code and Marking.SAP: 51070927.	1		
19-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 6 joints Casing 13-3/8"OD, 68 ppf, L-80, BTC, R 3.Open Protector, Cleaning Connection,FLD,FLBI,VTI,UTG,Internal Cleaning, Apply Thread Compound,Close Protector. External Cleaning /Coating. SAP: 50569927. and 12 joints Casing 13-3/8"OD, 68 ppf, K-55, TXP-BTC, R 3. SAP 51072151	1		
20-Apr-22	Lamongan Shorebase	08.00 - 17.00	Inspection and Maintenance 6 joints Casing 13-3/8"OD, 68 ppf, L-80, BTC, R 3. SAP: 50569927. and 12 joints Casing 13-3/8"OD, 68 ppf, K-55, TXP-BTC, R 3. SAP 51072151. Colour Code and Marking	1		
				TOTAL (Days)	10	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Chasan Musthopa
Personnel In Attendance

Contractor Representative

Rig Representative

The Company Representative