

PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance:

1. Chasan, 2. Rifaldi, 3. Reza, 4. Albert, 5. Levi, 6. Iskandar, 7. Swargi, Andik K.

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Sep-22

Period:

Sept 2022

Contract/ PO Non:

4710000000

Our Ref:

Service Date:

21 August - 20 Sept 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
21-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
22-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
23-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
24-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
25-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
26-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
27-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
28-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
29-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
30-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
31-Aug-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
1-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
2-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
3-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
4-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
5-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
6-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
7-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
8-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1

PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance:

1. Chasan, 2. Rifaldi, 3. Reza, 4. Albert, 5. Levi, 6. Iskandar, 7. Swargi, Andik K.

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Sep-22

Period:

Sept 2022

Contract/ PO Non:

4710000000

Our Ref:

Service Date:

21 August - 20 Sept 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
9-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
10-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
11-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
12-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
13-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
14-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.459".	RO No: 4500203800	1	1
15-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.459".	RO No: 4300071106	1	1
16-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
17-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300070173	1	1
18-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300070173	1	1
19-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300070173	1	1
20-Sep-22	Bunyu Field	08.00 - 17.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
TOTAL (Days)					31	31

Chasan Musthopa / Idham
Personnel In Attendance

Phony T. A.
Field Site Representative

The Company Representative