

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Yulius K**  
**Ermawan E**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **28-Nov-2021**

Periode : **Nov-Dec**

CRO No.:

Rig/Well : **SENIPAH**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			22-Nov	23-Nov	24-Nov	25-Nov	26-Nov	27-Nov		28-Nov
1	Chain Block	SNP		1					1	
2	Polyester Sling			7					7	
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
<b>PROVISION</b>										
7	Land Transportation	unit-day		1						1
8	Meal allowance	man-day		2						2

**Yulius K**  
Personnel In Attendance

Approved by PHM sites INS SPV