

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto**  
**Nico Achmad**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **8-Dec-2020**

Periode : **Des - Jan**

CRO No.: **0**

Rig/Well : **PTK - Tanjung Batu**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			2-Dec	3-Dec	4-Dec	5-Dec	6-Dec	7-Dec	8-Dec	
1	Cargo Carrying Unit		3	3	4	3	2	3	4	22
2	Shackle		5			4	12			21
3	Wire Rope Sling 3-leg or 4-legs		1			1	4	1		7
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	7
8	Meal allowance	man-day	2	2	2	2	2	2	2	14

**Pambudhi K/ Nico A.**  
Personnel In Attendance

**Dhany Ramdhan**  
Approved by PHM sites SPV