

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto**  
**Nico Achmad**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **24-Feb-2021**

Periode : **Feb-21**

CRO No.: **8532869**

Rig/Well : **NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			18-Feb	19-Feb	20-Feb	21-Feb	22-Feb	23-Feb	24-Feb	
1	Ginpole		7	8	2	8				25
2	Runway Beam				4	1	12	4	5	26
3	Slewing Jib Davit				2	5	1	2	3	13
4	Gantry							1		1
5	Pad Eye				7		4	4	7	22
6	Cargo Carrying Unit					1				1
7	Beam Trolley							2		2
7	Other Below The Hook Lifting Devices								4	4
9	Plate Handling Clamp								1	1
10										
11										
12										
13										
14										
15										

**Equipment Rental**

1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

**PROVISION**

7	Land Transportation	unit-day								
8	Meal allowance	man-day								

**Pambudhi Kristyanto**  
Personnel In Attendance

Bambang YUDIONO  
**25 FEB 2021**

**Bambang Yudiono**  
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto**  
**Nico Achmad**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **10-Mar-2021**

Periode : **March , 2021**

CRO No.: **8532869**

Rig/Well : **NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			4-Mar	5-Mar	6-Mar	7-Mar	8-Mar	9-Mar	10-Mar	
1	Runway Beam		3			5				8
2	Beam Trolley		3			1	1			5
3	Slewing Jib Davit		1			1				2
4	Ginpole		11	12	5		1			29
5	Lifting Frame With Pad Eye							2		2
6	Shackle							2		2
7	Chain Block						1			1
8										
9										
10										
11										
12										
13										
14										
15										


DEMOS FROM NPU


**Equipment Rental**

1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

**PROVISION**

7	Land Transportation	unit-day							1	1
8	Meal allowance	man-day								

  
**Pambudhi Kristyanto**  
 Personnel In Attendance

**Bambang YUDIONO**  
  
 09 MAR 2021  
**Bambang Yudiono**  
 Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto**  
**Nico Achmad**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **3-Mar-2021**

Periode: **Feb-21**

CRO No.: **8532869**


Rig/Well: **NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			25-Feb	26-Feb	27-Feb	28-Feb	1-Mar	2-Mar	3-Mar	
1	Runway Beam		3		3	5	3		12	26
2	Beam Trolley		1		1		2		1	5
3	Slewing Jib Davit		1		1	7	1		5	15
4	Ginpole		7	12	13	3	13	29	10	87
5	Pad Eye					7			1	8
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										

Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day								

  
**Pambudhi Kristyanto**  
 Personnel In Attendance

  
 Bambang YUDHONO  
 04 MAR 2021  
 Approved by PHM sites INS SPV