

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto
Agus salim asbar**

Customer: **PERTAMINA HULU
MAHAKAM**


Service Date: **22-Jun-2021**


Periode : **Mei - Jun**

CRO No.:

Rig/Well : **NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			16-Jun	17-Jun	18-Jun	19-Jun	20-Jun	21-Jun	22-Jun	
1	Runway Beam		10	4	8	14	7	10	12	65
2	Pad Eye		4	5	11		3		2	25
3	Slewing Jib Davit		1	2		3	2		1	9
4	Hydraulic Ram & Jack			1						1
5	Cargo Carrying Unit			1						1
6	Plate Handling Clamp			2						2
7	Beam Trolley				4	3	4	1	4	16
8	Other Below The Hook Lifting Devices					1		1		2
9	Chain Block					1	2			3
10	Shackle						1	7		8
11	Gantry						1		1	2
12	Chain Sling							1		1
13	Wire Rope Sling 1-leg or 2-legs							1		1
14	Spreader Bar							1		1
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day	1							1
8	Meal allowance	man-day	2							2


Pambudhi Kristyanto
 Personnel In Attendance

Bambang YUDIONO

 23 JUN 2021
Bambang Yudiono
 Approved by PHM sites INS SPV