

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:  
**Yulius K**  
**Usman K**

Customer:  
**PERTAMINA HULU**  
**MAHAKAM**

Service Date:  
**24-Mar-2021**

Periode : **Des - Mar**

CRO No.: **0**

Rig/Well : **Senipah**

No.	Service Description	Rig/Loc	Date of Inspection & Qty					TOTAL				
			18-Mar	19-Mar	20-Mar	21-Mar	22-Mar		23-Mar	24-Mar		
1	Slewing Jib Davit				1						1	
2	Wire Rope Sling 1-leg or 2-legs				6						6	
3	Wire Rope Sling 3-leg or 4-legs				1		1				2	
4	Cargo Carrying Unit						2	2			4	
5	Pad Eye						1				1	
6	Beam Trolley							1			1	
7	Runway Beam							1			1	
<b>Equipment Rental</b>												
1	Water bag 3 tonnes	unit-day										
2	Water bag 12 tonnes	unit-day										
3	Load Cell 5 tonnes	unit-day										
4	Load Cell 30 tonnes	unit-day										
5	Wire rope tester	unit-day										
<b>PROVISION</b>												
7	Land Transportation	unit-day			1		1				1	3
8	Meal allowance	man-day			2		3				3	8

*[Signature]*  
**Yulius K**  
Personnel In Attendance

*[Signature]*  
**IWAN S**  
Approved by PHM sites INS SPV