



Personnel In Attendance:

Pambudhi Kristiyanto  
Nico Achmad

Customer:

PERTAMINA HULU  
MAHAKAM

Service Date:

15-Dec-2020

Period :

Des - Jan

CRO No.:

0

Rig/Well :

PTK - Tanjung Batu

No.	Service Description	Rig/Loc	Date of Inspection & Qty					TOTAL	
			9-Dec	10-Dec	11-Dec	12-Dec	13-Dec		14-Dec
1	Cargo Carrying Unit		3	2	3	4	4	4	20
2	Shackle			8	8			8	36
3	Wire Rope Sling 3-leg or 4-legs			1	2			2	8
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
<b>PROVISION</b>									
7	Land Transportation	unit-day	1	1	1	1	1	1	6
8	Meal allowance	man-day	2	2	2	2	2	2	12

Pambudhi K/ Nico A.  
Personnel In Attendance

Juhazet Vemberius  
Approved by PHM sites SPV