

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

1. Suhardi Maricen
2. Ermawan Eka S

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

July 27, 2020

Periode :

July-2020

CRO No.:

4200139209

Rig/Well :

SPU BASE

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			21-Jul	22-Jul	23-Jul	24-Jul	25-Jul	26-Jul	27-Jul	
1	Pedestal Crane	SPU	1			1				2
2	Personnel & Good Lift	SPU	1							1
3	Slewing Jib Davit	SPU	2		2					4
4	Cargo Carrying Unit	SPU		2		1				3
5	Wire Rope Sling - 2 legs	SPU		2		1				3
6	Ginpole	SPU			9					9
7	Wire Rope Sling - 1 legs	SPU				1				1
8	Shackle	SPU				1				1
9	Runway Beam	SPU		1						1
11	Beam Trolley	SPU		1						1
12	Chain Block	SPU		1						1
13										0
14										0
15										0
16										0
17										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	1	1	1	1	1	1	1	7
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

Suhardi Maricen
Personnel In Attendance

Gunawan / A. Isyudanto
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1. Suhardi Maricen**
2. Ermawan Eka S

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **August 3, 2020**

Periode : **July-2020**

CRO No.: **4200139209**

Rig/Well : **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			28-Jul	29-Jul	30-Jul	31-Jul	1-Aug	2-Aug		3-Aug
1	Polyester Sling	SPU								0
2	Shackle	SPU								0
3	Pad eye	SPU								0
4	Snatch Block	SPU								0
5	Cargo Carrying Unit	SPU								0
6	Pedestal crane	SPU								0
7										0
8										0
9										0
11										0
12										0
13										0
14										0
15										0
16										0
17										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	1	1	1	1	1	1	1	7
PROVISION										
7	Land Transportation	unit-day	0	0	1	0	0	0	0	1
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

Suhardi Maricen
Personnel In Attendance

Isyudanto / Gunawan
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

1. Suhardi Maricen

Customer:

**PERTAMINA HULU
MAHAKAM**

Service
Date:

August 10, 2020

Periode :

August-2020

CRO No.:

4200139209

Rig/Well :

SPU BASE

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			4-Aug	5-Aug	6-Aug	7-Aug	8-Aug	9-Aug		10-Aug
1	Polyester Sling	SPU	2			1	1			4
2	Pad Eye	SPU	2	4	8	4				18
3	Shackle	SPU	16	8	8	8	4			44
4	Cargo Carrying Unit Including Lifting Set	SPU	1							1
5	Lifting Frame With Pad Eye	SPU	1	1			1			3
6	Cargo Carrying Unit	SPU		1					1	2
7	Wire Rope Sling 2-leg	SPU		3						3
8	Other Below The Hook Lifting Devices	SPU		4	3	4		1	6	18
9	Runway Beam	SPU						1		1
11	Chain Block	SPU						1		1
12										0
13										0
14										0
15										0
16										0
17										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	1	0	0	0	0	0	0	1
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	1	1
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

Suhardi Maricen
Personnel In Attendance

A.Isyudanto / Gunawan
Approved by PHM sites INS SPV