

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Yulius K
Andi Aan**

Customer: **PERTAMINA HULU
MAHAKAM**

Service Date: **7-Dec-2021**

Periode : **Des - Jan**

CRO No.:

Rig/Well : **Bekapai Field**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			1-Dec	2-Dec	3-Dec	4-Dec	5-Dec	6-Dec	7-Dec	
1	Chain Hoist		1					4		5
2	Wire Rope Sling 1-leg or 2-legs		2						6	8
3	Wire Rope Sling 3-leg or 4-legs		1						1	2
4	Shackle		2		14			6	4	26
5	Runway Beam			1				3		4
6	Pad Eye			2	8					10
7	Transportation Containers			1					1	2
8	Hooks				8			4		12
9	Jack				1					1
10	Crane include Pedestal Crane, Mobile Land Crane, Overhead crane						IP	1		1
11	Webbing Sling							4		4
12	Beam Trolley								1	1
13	Gantry								1	1
14	Slewing Jib / Davit								1	1
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	1	-	-	-	1
2	Water bag 12 tonnes	unit-day	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	-	-	1	-	-	-	1
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	
5	Wire rope tester	unit-day	-	-	-	-	1	-	-	1
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	
8	Daily Personnel allowance	man-day	-	-	-	-	-	-	-	

Yulius K

Personnel In Attendance

BUKTI H.
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: **Yulius K
Andi Aan**

Customer: **PERTAMINA HULU
MAHAKAM**

Service Date: **14-Dec-2021**

Periode : **Des - Jan**

CRO No.:


Rig/Well : **BKP FIELD**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			8-Dec	9-Dec	10-Dec	11-Dec	12-Dec	13-Dec		14-Dec
1	Gantry		1						1	2
2	Beam Trolley		1		1		1			3
3	Chain Hoist		3				1			4
4	Pad Eye		1		2					3
5	Shackle		6		3	4			4	17
6	Wire Rope Sling 1-leg or 2-legs		2			2	2		2	8
7	Crane include Pedestal Crane, Mobile Land Crane, Overhead crane			IP		IP	IP	1	1	2
8	Runway Beam			1			1	1	1	4
9	Transportation Containers				1		1			2
10	Webbing Sling				4					4
11	Wire Rope Sling 3-leg or 4-legs				1					1
12	Beam Clamp				1					1
13	Plate Clamp							2		2
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	1	-	-	-	-	-	1
2	Water bag 12 tonnes	unit-day	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	1	-	-	-	-	1	2
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	
5	Wire rope tester	unit-day	-	-	-	1	-	-	1	2
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	
8	Daily Personnel allowance	man-day	-	-	-	-	-	-	-	

Yulius K

Personnel In Attendance

Approved by PHM sites INS SPV

No.	TIK No.	Equipment Type	Detail Description	SWL (Ton)	LOCATION	INSPECTION DATE	PERFORMER	Color Code	Finding & Recommendation
8									
1	TIK-3-3036	Runway Beam	Runway- Free standing structure	0.5	BEKAPAI - BJ	15-12-2021	Yulius K	Infrequent Use/ fit for use	Runway beam was found rusty, shoul be clean up and repaint.
2	TIK-3-3457	Chain Hoist	Chain Block Single fall block	5	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
3	TIK-3-3458	Chain Hoist	Chain Block Single fall block	5	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
4	TIK-1311-3	Eyebolts	Eye Bolt	12	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
5	TIK-1312-3	Eyebolts	Eye Bolt	12	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
6	TIK-1313-3	Eyebolts	Eye Bolt	12	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
7	TIK-1314-3	Eyebolts	Eye Bolt	12	BKP-Tripod	15-12-2021	Yulius K	Fit For Use	
8	TIK-2589-2	Transportation Containers	Bottle Rack c/w 2 legs wire rope sling 22 mm Dia. x 1.800mm (13482-0), 2 ea Bow Shackle Bolt Type WLL 6.5 T (16702-0, 9592-0)	1	BKP-PP	15-12-2021	Yulius K	Fit For Use	Wire rope sling dry should be lubricated
Personnel In Attendance			Meal	Equipment	Qty	Prepared by PT. ISP Inspector		Approved by PHM sites INS SPV	
1	Yulius K			Water bag 3 tonnes		Date : 15 December 2021		Date :	
2	Andi Aan			Water bag 12 tonnes					
3			Load Cell 5 tonnes						
			Load Cell 30 tonnes						
	Transport			Wire rope tester		Yulius K			
CRO No.						Name & Signature		Name & Signature	