

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

24-Jan-2023

Periode :

JAN- FEB

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			18-Jan	19-Jan	20-Jan	21-Jan	22-Jan	23-Jan	24-Jan	
1	Jack	NPU	1				1	2		4
2	Chain Hoist	NPU	5			1				6
3	Eyebolts	NPU	21	20	10					51
4	Shackle	NPU	7		27	1	12	21	4	72
5	Crane include Pedestal Crane, Mobile Land Crane, Overhead crane	NPU		1						1
6	Runway Beam	NPU		1						1
7	Other Lifting Equipment Below The Hook	NPU				2				2
8	Webbing Sling	NPU				6	5		1	12
9	Wire Rope Sling 1-leg or 2-legs	NPU				4				4
10	Wire Rope Sling 3-leg or 4-legs	NPU				9				9
11	Elevator/ Lifts / Personnel Baskets	NPU					1			1
12	Ginpoles	NPU						1		1
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	1	1
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14

Deny Herzaldi
Personnel In Attendance

Bambang.Y/Pakop.D
Approved by PHM sites INS SPV