

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Suhardi Maricen**  
**2. Nico Achmad S**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **August 22, 2020**

Periode : **August-2020**

CRO No.: **4200139209**

Rig/Well : **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			21-Aug	22-Aug						
1	Pedestal Crane ( Verification Load Indicator Auxilliary Hoist Crane TIK-4-7173 WPS-2 - SPU )	SPU	IP							0
2	Pedestal Crane ( Wire Rope Tester Auxilliary Hoist Crane TIK-4-7173 WPS2 - SPU )	SPU		1						1
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	1	1	0	0	0	0	0	2
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	1	1	0	0	0	0	0	2
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	0	0	0	0	0	2
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

**Suhardi Maricen**  
Personnel In Attendance

**ISYUDANTO** Digitally signed by ISYUDANTO Athanatius  
DN:  
email=athanatius.isyudanto@phm.pertamina.com, cn=ISYUDANTO Athanatius  
**A. Isyudanto / Gunawan.A** Date: 2020.08.26 09:10:27 +08'00'

Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Suhardi Maricen**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **September 2, 2020**

Periode : **August-2020**

CRO No.: **4200139209**

Rig/Well : **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			27-Aug	28-Aug	29-Aug	30-Aug	31-Aug	1-Sep		2-Sep
1	Cargo Carrying Unit	SPU	2							2
2	Wire Rope Sling 2-leg	SPU	1							1
3	Ginpole	SPU		3	7	4	5	12	9	40
4	Runway Beam	SPU		1		4	1		2	8
5	Slewing Jib Davit	SPU		1		1			1	3
6										0
7										0
8										0
9										0
11										0
12										0
13										0
14										0
15										0
16										0
17										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	0	0	0	0	0	0	1
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

**Suhardi Maricen**  
Personnel In Attendance

**Gunawan / A. Isyudanto**  
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Suhardi Maricen**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **September 9, 2020**


Periode : **September-2020**

CRO No.: **4200139209**

Rig/Well : **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			3-Sep	4-Sep	5-Sep	6-Sep	7-Sep	8-Sep	9-Sep	
1	Runway Beam	SPU	1	1	2			1		5
2	Slewing Jib Davit	SPU	1	1						2
3	Ginpole	SPU	2	4	2	4	6		3	21
4	Beam Trolley	SPU						1		1
5	Wire rope sling 1 Leg	SPU						2		2
6	Powered Hoist	SPU						1		1
7	Chain Block	SPU						1		1
8										0
9										0
11										0
12										0
13										0
14										0
15										0
16										0
17										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
<b>PROVISION</b>										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

  
**Suhardi Maricen**  
 Personnel In Attendance

  
**Gunawan / A. Isyudanto**  
 Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Suhardi Maricen** Customer: **PERTAMINA HULU MAHAKAM** Service Date: **September 16, 2020**

Periode: **September-2020** CRO No.: **4200139209** Rig/Well: **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			10-Sep	11-Sep	12-Sep	13-Sep	14-Sep	15-Sep	16-Sep	
1	Wire Rope Sling 1-leg	SPU	4						1	5
2	Ginpole	SPU	1	4	5	4	4		1	19
3	Slewing Jib	SPU			1					1
4	Shackle	SPU							3	3
5	Plate Handling Clamp	SPU								7
6	Cargo Carrying Unit	SPU								1
7	Wire Rope Sling 4-leg	SPU								2
8										0
9										0
11										0
12										0
13										0
14										0
15										0
16										0
17										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
<b>PROVISION</b>										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	1
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

**Suhardi Maricen**  
Personnel In Attendance

**Gunawan / A. Isyudanto**  
Approved by PHM sites INS SPV