

# PT. INSPEKTINDO SINERGI PERSADA

## SERVICES TIME SHEET



Personnel In Attendance:	Pambudhi Kristyanto/ Reza Kukul	Customer:	Sulzer Balikpapan area	Date :	14-Jun-22
Period:	Jun-22	Contract/ PO Non:	RFI-22-015	Our Ref:	
Day Rate:		Rig / Well:	Balikipapan workshop		
Per Diem Rate :					

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	13-06-22	BPM Workshop	07.30 - 17.00	screw pin bow shackle NDT, Visual Examination	1		
2	14-06-22	—	—	Eye Bolt Pound sling, screw pin shackle NDT, Visual Examination	1		
<b>TOTAL (Days)</b>					2		
<b>TOTAL (USD)</b>							
<b>GRAND TOTAL</b>							

\* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark
1	13-06-22	Name plate - Tag ID	48	
		MPI SET	1	
		Paint Remover	1	
2		Permanent yoke	1	
	14-06-22	Name plate Tag ID	69	

*[Signature]*  
**PAMBUDHI KRISTYANTO**  
 Personnel In Attendance

\_\_\_\_\_  
 Contractor Representative

\_\_\_\_\_  
 Rig Representative

*[Signature]*  
 The Company Representative



## REQUEST FOR INSPECTION LIFTING GEARS & EQUIPMENTS

Date	: June 08, 2022	Ref No	: RFI-22-015
Customer	: PT SULZER	Delivery Date	: June , 2022
Contact Person	: Tata Subrata	Sales	: Cholidjah
PO Number	: PO-0056371		

**Description:** Conduct Inspection as per below SOW

Description			Scope of Work
Lifting Gear Inspection Services with Qty : <b>146 Item</b>			1. Review Document 2. Visual Inspection 3. Dimensional Conformity 4. NDT – MPI (Shackle Only) at Critical point area defined by competence person 5. ID Tag for Indication 6. Generate Report of Inspection
Item	Qty	UoM	
Eyebolt	68	Ea	
Shackle	52	Ea	
Webbing Sling	10	Ea	
Round Sling	16	Ea	
<b>Total</b>	<b>146</b>	<b>Ea</b>	

SWL: TBA

QTY : 146 Ea

Equipment Type	<input checked="" type="checkbox"/> Wire Rope Sling <input type="checkbox"/> Webbing Sling <input type="checkbox"/> A-Frame <input type="checkbox"/> Slings	<input checked="" type="checkbox"/> Spreader / Lifting Barr <input type="checkbox"/> Pad Eye <input type="checkbox"/> CCU <input type="checkbox"/> ILT	<input type="checkbox"/> Crane <input type="checkbox"/> Forklift <input checked="" type="checkbox"/> Lifting Gears : Eyebolt, Link
Scope of Work	<input checked="" type="checkbox"/> Review Documents <input checked="" type="checkbox"/> Visual Inspection <input type="checkbox"/> Functional Check <input checked="" type="checkbox"/> Dimensional Conformity		<input type="checkbox"/> Proof Load Test <input checked="" type="checkbox"/> NDT (MPI; PT; RI; UT Thickness; ECI) <input type="checkbox"/> Destructive Test <input type="checkbox"/> Hardness Test
Proof Load Applied	<input type="checkbox"/> 100% <input type="checkbox"/> 110% <input type="checkbox"/> 125% <input type="checkbox"/> 150% <input type="checkbox"/> 200% <input type="checkbox"/> SWL X 1.04 + 9.6 <input type="checkbox"/> SWL X 1.22 + 20 v Others		
Reference Standard	<input checked="" type="checkbox"/> BS Standard		
Location	<input type="checkbox"/> In-House (ISP) <input checked="" type="checkbox"/> Client Site: PT. Sulzer Indonesia Workshop Balikpapan		
Certification	<input checked="" type="checkbox"/> Thorough Inspection Report		<input type="checkbox"/> MILL CERT/ COC Product of Assembly
	<input type="checkbox"/> 3 <sup>rd</sup> Party Certification		<input type="checkbox"/> Government Certification
	<input type="checkbox"/> ABS <input type="checkbox"/> DNVGL <input type="checkbox"/> Lloyd Register <input type="checkbox"/> RINA	<input type="checkbox"/> BV <input type="checkbox"/> BKI <input type="checkbox"/> SUCOFINDO	<input type="checkbox"/> DISNAKER <input type="checkbox"/> MIGAS
	<input type="checkbox"/> Manufacturer COC		
Reporting	<input checked="" type="checkbox"/> Thorough Examination Report <input type="checkbox"/> Tensile Test Report <input checked="" type="checkbox"/> NDT Report		<input type="checkbox"/> DISNAKER Report <input type="checkbox"/> MIGAS Report <input type="checkbox"/> Tubular Inspection Report

Comments: