

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Deny Herzaldi
Andi Aan

Customer: PERTAMINA HULU
MAHAKAM

Service Date: 2-Aug-2022

Periode : JUN - JUL

CRO No.:

Rig/Well : HCA - HDL

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			27-Jul	28-Jul	29-Jul	30-Jul	31-Jul	1-Aug		2-Aug
1	Wire Rope Sling 1-leg or 2-legs	Handil				20			20	
2										
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	
8	Daily Personnel allowance	man-day	-	-	-	2	-	-	-	2

Deny Herzaldi
Personnel In Attendance

Ahmadan F/ Imam D.W
Approved by PHM sites INS SPV