

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:

1. Gunawan R.
2. Nico

Customer:

PERTAMINA HULU MAHAKAM

Service Date:

August 19, 2020

Periode:

August 2020

CRO No.:

Rig/Well:

PHM-Tanjung Batu

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			19-Aug							
1	Cargo Carrying Unit (lifting set)	Tanjung batu	1							1
2	PolyU	Tanjung betu	1							1
TOTAL			2	0	0	0	0	0	0	2
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
6	Land Transportation	unit-day	1	0	0	0	0	0	0	1
7	Meal allowance	man-day	2	0	0	0	0	0	0	2

Gunawan R.

Personnel In Attendance

Jufarman MEMBERIUS
ISA YONG OPP. SPV
Approved by PHM sites INS SPV