

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Suhardi Maricen**
Ermawan Eka S

Customer: **PERTAMINA HULU**
MAHAKAM


Service Date: **8-Jun-2021**


Periode: **Jun - Jul**

CRO No.:

Rig/Well: **BEKAPAI**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			2-Jun	3-Jun	4-Jun	5-Jun	6-Jun	7-Jun	8-Jun	
1	Cargo Carrying Unit	BKP		1						1
2	Beam Clamp	BKP		2				2		4
3	Polyester Sling	BKP		1		1		3	1	6
4	Shackle	BKP		2	12	7	6	16	9	52
5	Chain Block	BKP			4				1	5
6	Other Below The Hook Lifting Devices	BKP			4			1	4	9
7	Eye Bolt	BKP			4		4			8
8	Pedestal Crane	BKP				1				1
9	Runway Beam	BKP		1		1	1	1		4
10	Beam Trolley	BKP				1	1		1	3
11	Gantry	BKP					1		1	2
12	Wire Rope Sling 1-leg or 2-legs	BKP					2		5	7
13	Slewing Jib Davit	BKP						1		1
14	Wire Rope Sling 3-leg or 4-legs	BKP							2	2
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day				1				1
PROVISION										
7	Land Transportation	unit-day		1						1
8	Meal allowance	man-day		2	2	2	2	2	2	12


Suhardi Maricen
 Personnel In Attendance


 Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1.Suhardi Maricen**
2.Ermawan Eka S

Customer: **PERTAMINA HULU**
MAHAKAM


Service Date: **15-Jun-2021**


Periode : **Jun - Jul**

CRO No.:

Rig/Well : **BEKAPAI**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			9-Jun	10-Jun	11-Jun	12-Jun	13-Jun	14-Jun		15-Jun
1	Beam Clamp	BKP					1		1	
2	Cargo Carrying Unit	BKP	2	2	2	1		3	1	11
3	Chain Block	BKP					2	1		3
4	Gantry	BKP			1			1		2
5	Hydraulic Ram & Jack	BKP	1							1
6	Other Below The Hook Lifting Devices	BKP	3	3			5		4	15
7	Pad Eye	BKP	8				4			12
8	Plate Handling Clamp	BKP		2		1				3
9	Polyester Sling	BKP		1	5	14			3	23
10	Runway Beam	BKP			1			2	1	4
11	Shackle	BKP	5	4	6		4		10	29
12	Wire Rope Sling 1-leg or 2-legs	BKP	5	3	1					9
13	Wire Rope Sling 3-leg or 4-legs	BKP	1							1
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day	2	2	2	2	2	2	2	14


Suhardi Maricen
Personnel In Attendance


Joko S / Bukti H
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Suhardi Maricen**
Ermawan Eka S

Customer: **PERTAMINA HULU**
MAHAKAM

Service Date: **22-Jun-2021**

Periode : **Jun - Jul**

CRO No.:

Rig/Well :

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			16-Jun	17-Jun	18-Jun	19-Jun	20-Jun	21-Jun		22-Jun
1	Cargo Carrying Unit	BKP	1			2	1		4	
2	Lever Hoist	BKP	2						2	
3	Runway Beam	BKP	1	1	2	1	1		6	
4	Snatch Block	BKP	2						2	
5	Slewing Jib Davit	BKP		1					1	
6	Beam Trolley	BKP	1	1					2	
7	Beam Clamp	BKP					1		1	
8	Wire Rope Sling 1-leg or 2-legs	BKP		2					2	
9	Gantry	BKP		1					1	
10	Shackle	BKP		6		4	1		11	
11	Wire Rope Sling 3-leg or 4-legs	BKP				1			1	
12	Chain Block	BKP			3				3	
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day	2	2	2	2	2		10	

Suhardi Maricen
Personnel In Attendance

Approved by PHM sites INS SPV