


WORK TIME SHEET


Employee Name: FX BERNANDO SAGALA (INSPECTOR) DONI KATMEL CASST/NDT (INSPECTOR)	RFI Number: RFI 22-025	Location: BIGLIFT VESSEL - PTMM YARD
Customer Name: PT. McDERMOTT INDONESIA		PO/WO Number:

Date & Day	Scope of Work	Start Time	Finish Time
MARCH 24, 2022	1. CONDUCT EDDY CURRENT OF MAIN HOIST 2. CONDUCT VISUAL WIRE ROPE INSPECTION ON: - BDM HOIST - MAIN HOIST	07.00	17.00

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark
MARCH 24, 2022	1. EDDY CURRENT - 1 SET	

Client Signature :  Date : 24 MAR 2022
 Name : IRA WALAYANA GINTING
 Company : McDERMOTT

Employee Signature : 

Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com



Management System
 ISO 9001:2015
 www.tuv.com
 ID 9105063224



WORK TIME SHEET


Employee Name: FX PERNANDO SAGALA DAMI KATMEL SITANGGANG	RFI Number:	Location: PTM YARD - 66LIFT VESSEL
Customer Name: PT. McDERMOTT INDONESIA		PO/WO Number:

Date & Day	Scope of Work	Start Time	Finish Time
MARCH 26, 2022	# CONDUCT ECI FOR MAIN HOOR CRANE #2 HAPPY STAR VESSEL	12.00	
	# CONDUCT VISUAL INSPECTION :		
	a. MAIN HOIST		
	b. BOOM HOIST		13.00

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark
MARCH 26, 2022	EDDY CURRENT	1 SET

Client Signature : IRA V. GINTING Date : 26 MAR 2022
 Name : DM
 Company : MDR

Employee Signature : 

P.s. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com



Management System
 ISO 9001:2015
 www.tuv.com
 ID 9105002224



WORK TIME SHEET

Employee Name: FX Fernando Sagala	RFI Number:	Location: PTMI Yard – Batam (Biglift Vessel)
Customer Name: PT. McDermott Indonesia		PO/WO Number: -

Date & Day	Scope of Work	Start Time	Finish Time
30-Mar-22 & Wednesday	Conduct wire rope inspection for main hoist of crane#1 of Happy Star Vessel	10.00	12.00

Consumable Material Usage