

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

**Deny Herzaldi**  
**Andi Aan**

Customer:

**PERTAMINA HULU**  
**MAHAKAM**

Service Date:

**26-Jul-2022**

Periode :

**JUN - JUL**

CRO No.:

Rig/Well :

**NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			20-Jul	21-Jul	22-Jul	23-Jul	24-Jul	25-Jul	26-Jul	
1	Shackle	NPU	12							12
2	Wire Rope Sling 3-leg or 4-legs	NPU	3							3
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	-	-	-	-	-	-	1
8	Daily Personnel allowance	man-day	2	-	-	-	-	-	-	2

**Deny Herzaldi**  
Personnel In Attendance

**Bambang Yudiono**

Approved by PHM sites INS SPV