

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: M. Arya Wachid A. - Thoro S. - Mahfud
 Period: June - July 2023
 Day Rate: -
 Per Diem Rate: -

Customer: SLB - Well Construction Drilling
 Contractor/ PO Non: -
 Rig/ Well: Cikarang Integrated Base

Date: -
 Out Ref: -
 Form No: -

Billing Date	Rig/ Loc ^a	Time ^a	ACTIVITY (TOOL NAME_SHR_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_Ex Machine Shop	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
26/06/2023	CIB	08.30 - 17.30	8.5 K5618 - JF383L, 12.25 SD519MHSPX - JF8906, 12.25 SD519MHSPX - JN721D & 17.5 MD519LHSPX - JN8282 at PT IMECD (Inspection)	8	WCD_BOT_BIT * (27/06/2023)	-	WCD	
27/06/2023	CIB	08.30 - 17.30	8 1/2 Kelly Mandrel - U94149 (Inspection); HJ475-54244H & HJ475-81862H (Cleaning)	8	WCD_BOT_AFTER REPAIR (26/06/2023), WCD_BOT_HJ475-54244H (27/06/2023) & WCD_BOT_HJ475-81862H (27/06/2023)	-	WCD	
28/06/2023	CIB	08.30 - 17.30	HJ475-54244H & HJ475-81862H - Witnessed by Medco (Inspection);	8	WCD_BOT_HJ475-54244H (27/06/2023) & WCD_BOT_HJ475-81862H (27/06/2023)	-	WCD	
30/06/2023	CIB	08.30 - 17.30	LS 475 - 9153789-002 (Inspection); WP - M2190 & Parts, XO - KSU165-16856-010L, XO / Extension - GFS 598279-4, Valve Housing - 19A & 19E, Stand of Sleeve - 19C, Stand of Ring - 19D & Cup Screen - 19E Witnessed by SAKA (Inspection)	8	WCD_BOT_AFTER REPAIR (26/06/2023), MI-ST-071023-WBCO-MUBADALA-HARBOUR (16-Jul-2023) & MI-ST-051623-AR-SAKA (21/06/2023)	-	WCD	
TOTAL (hours)								

^aIf Applicable

Thoro & Mahfud
ISP Personnel in Attendance

Wachid
ISP Inspector

Fairul
SLB Maintenance Technician

Yogi-A
SLB Maintenance Supervisor