



# INSPECTION REQUEST FORM

## QAQC DRILLING & WELL INTERVENTION

Doc N <sup>o</sup>	:	DWI-QAQC-FORM-006
Revision	:	00
Page	:	1 of 1

### 1. Inspection Information

Requester	:	PT. Mulia Jaya Mandiri						
Contract N <sup>o</sup>	:	KTAD-DC-102S						
Purchase Order/Work Order	:	038/MJM/VOC-A/XI/2021, 039/MJM/VOC-A/XI/2021, 010/MJM/VOC-A/XII/2021						
Inspection Perform Date	:	Mon	Tue	Wed	Thu	Fri	Sat	Sun
					09-Dec-2021			
Supplier/Contractor	:	PT. Mulia Jaya Mandiri						
Inspection Location	:	PT. Mulia Jaya Mandiri						
Contact Person	:	Pak Win						
		Pak Budi						
Well Allocation	:	SAPI Well Campaign, YN-30 & YN-31, YNB						
Material/Tool/Equipment	:	X.over 9-5/8" 53.5ppf P-110 TSH BLUE X PC-22, 9 FT (2 EA)						
		X.Over 3-1/2" L-80 13%CR 9.2ppf TSH BLUE x TKC, 4 FT (2 EA)						
		Threading 7" 29tpf Special Drift TSH BLUE Box on Reamer Shoe (3 EA)						

### 2. Scope Inspection Perform

Please to note in here the inspection scope and if any concern to be specially performed by QAQC personnel(s).

Visual Inspection

Request by Contract Owner/Project Engineer	Request by Vendor/Services Company	Approved by QAQC Engineer/Coordinator
	Reva Yustia	Ardi Septiawan
	sales@muliajayamandiri.com	ardi.septiawan@pertamina.com