

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Bernard & Team** Customer: **PETRONAS** Date: **20-Oct-21**
 Period: **Oct-21** Contract/ PO Non: _____ Our Ref: _____
 Day Rate: _____ Rig / Well: **Petronas (Lamongan Shore Base)** Form No. : _____
 Per Diem Rate : _____

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
01/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
02/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
03/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
04/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
05/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
06/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
07/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
08/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
09/10/2021	LSB	08.00-17.00	Inspection Casing, 30" x 1.5" WT, 475 PPF,X-56, PUMA DF, BOX UP x PIN DOWN R-3	1		
10/10/2021	LSB	08.00-17.00	Inspection Casing, 30" x 1.5" WT, 475 PPF,X-56, PUMA DF, BOX UP x PIN DOWN R-3	1		
11/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
12/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
13/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
14/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
15/10/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TP-QR CONNECTION R-3	1		
16/10/2021	LSB	08.00-17.00	Inspection Casing, 18 5/8" OD,87.5 PPF, K55, TP-QR CONNECTION R-3	1		
17/10/2021	LSB	08.00-17.00	Inspection Pup Joint & X-over,18 5/8" OD,87.5 PPF, K55, TP-QR , 15 Ft & 8 Ft	1		
18/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
19/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
20/10/2021	LSB	08.00-17.00	Inspection Tubing, 3 1/2" OD, 9.2 PPF, L80, VAM TOP, R-2	1		
TOTAL (Days)				20		
TOTAL (USD)						
GRAND TOTAL						

* If Applicable



Personnel In Attendance

Contractor Representative

Rig Representative

The Company Representative