


WORK TIME SHEET

Employee Name: - Muhammed Firdly (Crane Inspector) - Darmendra (Ass. Inspector)	Ref. Number:	Location: SIKB Yard
Customer Name: PT. AVER ASIA		PO/WO Number:

Date & Day	Scope of Work	Start Time	Finish Time
October 05, 2021	- Function test & Load test 1 unit Boom lift SM: SX 125-5	07:00	16:00

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark
	 	
	 	
	 	

Client Signature :  Date : 05-10-2021
 Name : Barkun
 Company : 05-10-2021 PT AVER ASIA

Employee Signature : 

Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com




WORK TIME SHEET


Employee Name: - Muhammed Fudky (Crane Inspector) - Darmendra (Ass. Inspector)	Ref. Number:	Location: SIKB Yard.
Customer Name: PT. AVER ASIA.	PO/WO Number:	

Date & Day	Scope of Work	Start Time	Finish Time
October 09, 2021	- function test 2 unit air Compressor & 3 unit air dryer SN: C1000-5, C9187 D36, D37 & D17.	07:00	
	- function test & load test 1 unit Boom lift SN: S125-5		16:00

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark

Client Signature :  Date : 09-10-2021
 Name : Barkun
 Company : PT AVER ASIA

Employee Signature : 

Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com




WORK TIME SHEET

Employee Name: - Muhammad Fhadly (Crane Inspector) - Darmendra (Ass. Inspector)	Ref. Number:	Location: SIKB Yard.
Customer Name: PT. AVERZ Asia	PO/WO Number:	

Date & Day	Scope of Work	Start Time	Finish Time
October 03, 2021	- Visual inspection 5 unit air Compressor SN: C9187, C1000-2, C1000-3, C1000-4, C1000-5	07:00	
	- Visual inspection 5 unit Air Dryer SN: D30, D38, D36, D37, D17		
	- Visual inspection 2 unit Boom lift. SN: S125-5 & SX 125-5.		
	- Function test 3 unit air Compressor & 2 unit Air Dryer SN: C1000-2, C1000-3, C1000-4 & D30, D38.		16:00.

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark

Client Signature :  Date : 05-10-2021
 Name : Bacem
 Company : PT AVERZ Asia

Employee Signature : 

Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com




WORK TIME SHEET

Employee Name: - MUHAMMAD FHADLY (Crane Inspector) - DARMENDRA (Ass. Inspector)	Ref. Number:	Location: SIKB Yard.
Customer Name: PT. AVER ASIA	PO/WO Number:	

Date & Day	Scope of Work	Start Time	Finish Time
October 02, 2021	- MOB From Batam to SIKB Yard.	07:00	10:00
	- Doc Review & Preparation for Inspection	10:00	
	- Waiting Equipment transfer to Inspection Area.		16:00

Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark
	 	
	 	
	 	
	 	

Client Signature :  Date : 05-10-2021
 Name : Batman
 Company : PT. AVER ASIA

Employee Signature : 
 M. FHADLY

Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 324747 / 324749
 Fax : +62 (0) 778 321338
 Email : sales@rigspekperkasa.com
 Website : www.rigspekperkasa.com

