

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

1. Gunawan R.
2. Abdillah M.

Customer:

PERTAMINA HULU MAHAKAM

Service Date:

20 July 2020

Periode :

July 2020

CRO No.:

4200139209

Rig/Well :

NORTH PROCESSING UNIT

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			14-Jul	15-Jul	16-Jul	17-Jul	18-Jul	19-Jul	20-Jul	
1	Shackle	NPU	8							8
2	Chain block	NPU		1			10			11
3	Ginpole	NPU	1							1
4	Cargo Carrying Unit including lifting set	NPU	1							1
5	Wire rope sling 3-leg or 4-leg	NPU	4							4
6	Hydraulic Ram & Jack	NPU			1					1
7	Forklift	NPU				1				1
8	Overhead crane	NPU		1						1
9	Polyster sling	NPU			12	14				26
10	Beam Clamp	NPU		5						5
TOTAL			14	7	13	15	10	0	0	59
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
6	Land Transportation	unit-day	0	0	0	0	0	0	0	0
7	Meal allowance	man-day	0	0	0	0	0	0	0	0

Gunawan R.

Personnel In Attendance

Bambang Y

Approved by PHM sites INS SPV