

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
25-Mar-24	Manggar Base	08.00 - 12.00	PD6 CONTROL COLLAR SLEEVE - 100398083 - JOP22-OSS-008 - Inspection	8	WCM_PDORB675_26 March, 2024_SN104940		DNM	
		13.00 - 16.00	EXTENSION COLLAR, PDX6 - 107749 - Inspection		WCM_PDORB675_26 March, 2024_SN104940			
			MSSA - MSSA-EC, CROSSOVER SUB, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - 01P0003279-25-2 - Inspection		Gryodata_25 March 2024_GWD6_after backloaded			
			MSSA - MSSA-BC, CROSSOVER SUB, M10, 5-1/2 FH BOX X 5-1/2 FH PIN, STAINLESS STEEL - 01P0002347-1-1 - Inspection		Gryodata_25 March 2024_GWD6_after backloaded			
			Gyro Collar - 675 Gyrodata Collar - 01P0002275-3-4 - Inspection		Gryodata_25 March 2024_GWD6_after backloaded			
				TOTAL (hours)	8			

* If Applicable

Mangiring, Christoper, Sarwo
Personnel In Attendance

Mangiring
ISP Inspector

05/04/24

 SLB Maintenance Technician

Dani Riyantoso
 SLB Maintenance Supervisor