

PT. INSPEKTINDO SINERGI PERSADA

SERVICES TIME SHEET



Personnel In Attendance: <u>M. F. HADLY, DARMENDRA & ELICOTTEN</u>	Customer: <u>PT. TAKA HYDROCORE INDONESIA</u>	Date: <u>JAN 26, 2023</u>
Period: <u>JAN 2023</u>	Contract/ PO Non: <u></u>	Our Ref: <u>RFI 23-007</u>
Day Rate: <u></u>	Rig / Well: <u>ON BOARD SS BARACUDA</u>	
Per Diem Rate: <u></u>		

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	Jan 20, 2023	SS BARACUDA	08 ⁰⁰ -	Conduct Visual Inspection, NDT Inspection & functional test	1		
2	Jan 21, 2023	- " -	08 ⁰⁰ -	Conduct Visual Inspection, NDT Inspection & functional test	1		
3	Jan 22, 2023	- " -	08 ⁰⁰ -	Conduct Visual Inspection, NDT Inspection & install ID Tag	1		
4	Jan 24, 2023	- " -	08 ⁰⁰ -	Conduct Visual Inspection, NDT Inspection, functional test & light load test	1		
TOTAL (Days)					4		
TOTAL (USD)							
GRAND TOTAL							

* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark
	Jan 20, 2023	NDT Eddy current Equipment 1 set	2	Days
	to	MP-35 white contrast paint & SM-15 Black Ink (for NDT MPI)	1	Set
		ID Tag 03	13	EA
	Jan 24, 2023			

MUHAMMAD FHADLY
 Personnel In Attendance

Contractor Representative

Rig Representative

MUHAMMAD FHADLY
 The Company Representative

