

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:

Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
14-Dec-23	Manggar Base	08.00 - 12.00	Motor Catcher Stem - 962 MOTOR CATCHER STEM, W/FLOW BYPASS, 6" TO 10" - 127130-1 - Inspection	8	MotorExtraPart_14Dec23		DNM	
		13.00 - 17.00	Stabilizer - STABILIZER, 17-1/4 GAUGE, 5" CROWN LG, STRAIGHT - RIB12-354-OSS - Inspection		SleeveStabilizer17.25HS_13Dec23			
			Pony Collar - Drill Collar, >=8"OD, Pony, Non-Mag, Straight - 4452 - Inspection		To Be Created			
			Rotor - R700786 8-PCHR-1.00 BORE-3.50 HUGHES SLIMLINE H-90 - 5833B0 - Inspection		Stator_Rotor_A700M_12Dec23			
			Lifting Sub - Lift Sub, >=6"OD, Steel - 4 1/2-IFP_RIB11-230 - Inspection		To Be Created			
			MUD MOTOR SLEEVE - STAB,25-3/4 GD,WELDED STRAIGHT BLADE, A962 & A1125 MOTORS - JCP12-OSS-084 - Inspection		To Be Created			
			X-Over RIB23-102-BBS - Ex Machine Shop		To Be Created			
TOTAL (hours)				8				

* If Applicable

Mangiring, Sarwo, Christopher
 Personnel In Attendance

Mangiring
 ISP Inspector

SLB Maintenance Technician

Doni Daryanto
 SLB Maintenance Supervisor