

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Deny Herzaldi**
A Wahyu
A. Fuad K

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **17/12/2020 - 23/12/2020**

Periode : **Nov - Jan**

CRO No.: **0**

Rig/Well : **HCA SITE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			17-Dec	18-Dec	19-Dec	20-Dec	21-Dec	22-Dec		23-Dec
1	Cargo Carrying Unit	HDL			5	7				12
2	Shackle	HDL-CPA	4	20						24
3	Polyester Sling	HDL		6						6
4	Other Below The Hook Lifting Devices	CPA		1	1				6	8
5	Runway Beam	CPA		3			3	6	4	16
6	Chain Block	CPA	1	2			4	4		11
7	Powered Hoist	CPA		1			1	2	2	6
8	Beam Trolley	CPA		2			1			3
9	Slewing Jib Davit	CPA		3					1	4
10	Wire Rope Sling 1-leg or 2-legs	CPA	1							1
11	Spreader Bar	CPA	1							1
12	Pad Eye	CPA						6		6
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day	1	1	1	1	1	1	1	7
8	Meal allowance	man-day	2	3	3	3	3	3	3	20

Deny Herzaldi
Personnel In Attendance

Ahmadan F / Abu Khoiri
Approved by PHM sites INS SPV