

PT. INSPEKTINDO SINERGI PERSADA

SERVICES TIME SHEET



Personnel In Attendance:	1. Erwin Nugraha 2. Reza Achmad	Customer:	PERTAMINA HULU MAHAKAM	Service Date:	5-Jan-2021
Periode :	Des - Jan	CRO No.:	8532803	Rig/Well :	CPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			30-Dec	31-Dec	1-Jan	2-Jan	3-Jan	4-Jan	
1	Wire Rope Sling 3-leg or 4-legs		4	3			2		9
2	Shackle			8			8	4	20
3	Runway Beam				5	2		1	10
4	Slewing Jib Davit				1	3			4
5	Chain Block					2	2		4
6	Wire Rope Sling 1-leg or 2-legs					1	2		3
7	Beam Clamp					1			1
8	Pad Eye						2		2
9	Beam Trolley							2	2
10									
11									
12									
13									
14									
15									

Page 1

Equipment Rental									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day				1	1		2
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							

PROVISION									
7	Land Transportation	unit-day							
8	Meal allowance	man-day							

Erwin Nugraha Personnel In Attendance					Mulyadi / Agus Elfiana Approved by PHM sites INS SPV				
--	--	--	--	--	---	--	--	--	--

PT. INSPEKTINDO SINERGI PERSADA

SERVICES TIME SHEET



Personnel In Attendance:	1. Erwin Nugraha 2. Reza Achmad	Customer:	PERTAMINA HULU MAHAKAM	Service Date:	12-Jan-2021
Periode :	Des - Jan	CRO No.:	8532803	Rig/Well :	CPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			6-Jan	7-Jan	8-Jan	9-Jan	10-Jan	11-Jan	12-Jan	
1	Beam Trolley		5	1						6
2	Shackle		4		10	10	14	16		54
3	Runway Beam		5	5						10
4	Slewing Jib Davit									
5	Chain Block		2	1					2	5
6	Wire Rope Sling 1-leg or 2-legs				1					1
7	Lever Hoist								1	1
8	Hydraulic Ram & Jack			1						1
9	Wire Rope Sling 3-leg or 4-legs				1		1			2
10	Forklift				1					1
11	Plate Handling Clamp						4			4
12	Sperader Bar						1			1
13	Lifting Frame With Pad Eye						1			1
14	Hook							4		4
15	Polyester Sling								4	4

Page 1

Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day							1	1
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day								

Personnel In Attendance	Erwin Nugraha									Mulyadi / Agus Elfiana
										Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA

SERVICES TIME SHEET



Personnel In Attendance:	1. Erwin Nugraha 2. Reza Achmad	Customer:	PERTAMINA HULU MAHAKAM	Service Date:	19-Jan-2021
Periode :	Des - Jan	CRO No.:	8532803	Rig/Well :	CPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			13-Jan	14-Jan	15-Jan	16-Jan	17-Jan	18-Jan	19-Jan	
1	Cargo Carrying Unit		3	3		3		1		10
2	Wire Rope Sling 1-leg or 2-legs			2		2				4
3	Shackle				8		4			12
4	Chain Block				2					2
5	Polyester Sling					7				7
6	Wire Rope Sling 3-leg or 4-legs					1				1
7	Runway Beam						2			2
8	Pedestal Crane								1	1
9	0									
10	0									
11	0									
12	0									
13	0									
14	0									
15	0									

Page 1

Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day							1	1
3	Load Cell 5 tonnes	unit-day			1				1	2
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day								

Erwin Nugraha			Mulyadi / Agus Elfiana							
Personnel In Attendance			Approved by PHM sites INS SPV							