

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

**Deny Herzaldi**  
**Ermawan E.S**

Customer:

**PERTAMINA HULLU**  
**MAHAKAM**

Service Date:

**23-Nov-2021**

Periode :

Nov - Des

CRO No.:

Rig/Well :

SPS

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			17-Nov	18-Nov	19-Nov	20-Nov	21-Nov	22-Nov	
1	Spreader Bar	SPS	1						1
2	Runway Beam	SPS	1						1
3	Gantry	SMK-DM 1		1					1
4	Pad Eye	SMK-JM 1			12		18		30
5	Shackle	SMK-JM 1				18			18
6	Hooks	SMK-JM 1				4			4
7									
8									
9									
10									
11									
12									
13									
14									
15									
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day	1	1					2
5	Wire rope tester	unit-day							
<b>PROVISION</b>									
7	Land Transportation	unit-day	1	1	1	1			4
8	Daily Personnel allowance	man-day	2	2	2	2			8

*Handwritten signature*

**Deny Herzaldi**

Personnel In Attendance

Iwan Setiawan / Abu Khoiri

Approved by PHM sites INS SPV