

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: **Yulius K
Ermawan Eka S**

Customer: **PERTAMINA HULU
MAHAKAM**

Service Date: **9-Aug-2022**

Periode : **JUL - AUG**

CRO No.:

Rig/Well : **SPU AREA**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL	
			3-Aug	4-Aug	5-Aug	6-Aug	7-Aug	8-Aug	9-Aug		
1	Transportation Containers			1	1			1		3	
2	Shackle			8					5	13	
3	Beam Clamp				4			1		5	
4	Chain Hoist				2		3	1	1	7	
5	Lever Hoist				1					1	
6	Other Lifting Equipment Below The Hook				6			4		10	
7	Wire Rope Sling 1-leg or 2-legs				3					3	
8	Wire Rope Sling 3-leg or 4-legs				1					1	
9	Webbing Sling					14			1	15	
10	Beam Trolley						3			3	
11	Elevator/ Lifts / Personnel Baskets							1		1	
12	Eyebolts								1	1	
13											
14											
15											
Equipment Rental											
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-	
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-	
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-	
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-	
PROVISION											
7	Land Transportation	unit-day	-	1	-	-	-	-	-	1	2
8	Daily Personnel allowance	man-day	-	2	2	2	2	2	2	2	12

Yulius K
Personnel In Attendance

A. Isyudanda
Approved by PHM sites INS SPV