




DAILY INSPECTION REPORT



Name & address of employer for whom the thorough examination was made: SLB Jl.Mulawarman,Km 20. Manggar Balikpapan 76117 East Kalimantan Indonesia	Address of premises at which the examination was made: Muara Badak & Unit 2340 Wireline	Contract No. :	
		Date of inspection : 25-26 July 2023	
		Report No :	Page 1 of 5

No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remarks and Recommendation
No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remark and Recommendation
1.	Lubricator Lifting Clamp. Size : 5 Inch SWL: 2 ton ID: LEED 8932	LOLER	Thorough Examination (Visual & NDT) VN	- Good Condition	Fit for use

I hereby certify that on the date(s) mentioned above, the items described in this report were thoroughly examined so far as was accessible and the particulars given above are correct

Name of the person making this report: Wahyudhi  Qualification of Inspector : CI, LGI, ASNT Level II MT&PT Qualification of Inspector: Company Approved	Name of the person authenticating this report: Signature:	Name & address of employer of persons making and authenticating this report: PT. Inspektindo Sinergi Persada Kawasan Industri Sekupang Kav.No. 13 Batam 29428 – Indonesia Tel : +62 778 326103 / 326104 Fax : +62 778 321388 Email : sales@inspektindo.com
--	--	---

PT. Inspektindo Sinergi Persada
 Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel : +62 (0) 778 326103/326104
 Fax : +62 (0) 778 321338
 Email : sales@inspektindo.com
 Website : www.inspektindo.com
Page 1 of 5

Form No.: ISP/REP/092/Rev.01






DAILY INSPECTION REPORT



Name & address of employer for whom the thorough examination was made: SLB Jl.Mulawarman,Km 20. Manggar Balikpapan 76117 East Kalimantan Indonesia	Address of premises at which the examination was made: Muara Badak & Unit 2340 Wireline	Contract No. :	
		Date of inspection : 25-26 July 2023	
		Report No :	Page 2 of 5

No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remarks and Recommendation
2.	Single leg wire rope sling in 16 mm diameter wire, thimble eyes each end captivated with Safety pin bow shackle WLL : 3.25 ton SWL: 3.25 ton ID: LEE 03964	BS EN 13414-2	Thorough Examination (Visual) V	- Broken Wires	Unfit for use

I hereby certify that on the date(s) mentioned above, the items described in this report were thoroughly examined so far as was accessible and the particulars given above are correct

Name of the person making this report: Wahyudhi  Qualification of Inspector : CI, LGI, ASNT Level II MT&PT Qualification of Inspector: Company Approved	Name of the person authenticating this report: Signature:	Name & address of employer of persons making and authenticating this report: PT. Inspektindo Sinergi Persada Kawasan Industri Sekupang Kav.No. 13 Batam 29428 – Indonesia Tel : +62 778 326103 / 326104 Fax : +62 778 321388 Email : sales@inspektindo.com
--	--	---

PT. Inspektindo Sinergi Persada
 Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel :+62 (0) 778 326103/326104
 Fax :+62 (0) 778 321338
 Email : sales@inspektindo.com
 Website : www.inspektindo.com
Page 2 of 5

Form No.: ISP/REP/092/Rev.01






DAILY INSPECTION REPORT



Name & address of employer for whom the thorough examination was made: SLB Jl.Mulawarman,Km 20. Manggar Balikpapan 76117 East Kalimantan Indonesia	Address of premises at which the examination was made: Muara Badak & Unit 2340 Wireline	Contract No. :	
		Date of inspection : 25-26 July 2023	
		Report No :	Page 3 of 5

No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remarks and Recommendation
3.	- BOP Cage ID: SLB 03667 - Grease Module ID: LEED 8660 - Frame PCE ID: LEE 09996 - Tie Down Chain ID: LEE 02031	-	-	-	Change Colour Code Only Last Inspection on June 2023

I hereby certify that on the date(s) mentioned above, the items described in this report were thoroughly examined so far as was accessible and the particulars given above are correct

Name of the person making this report: Wahyudhi  Qualification of Inspector : CI, LGI, ASNT Level II MT&PT Qualification of Inspector: Company Approved	Name of the person authenticating this report: Signature:	Name & address of employer of persons making and authenticating this report: PT. Inspektindo Sinergi Persada Kawasan Industri Sekupang Kav.No. 13 Batam 29428 – Indonesia Tel : +62 778 326103 / 326104 Fax : +62 778 321388 Email : sales@inspektindo.com
--	--	---

PT. Inspektindo Sinergi Persada
 Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel :+62 (0) 778 326103/326104
 Fax :+62 (0) 778 321338
 Email : sales@inspektindo.com
 Website : www.inspektindo.com
Page 3 of 5

Form No.: ISP/REP/092/Rev.01






DAILY INSPECTION REPORT



Name & address of employer for whom the thorough examination was made: SLB Jl.Mulawarman,Km 20. Manggar Balikpapan 76117 East Kalimantan Indonesia	Address of premises at which the examination was made: Muara Badak & Unit 2340 Wireline	Contract No. :	
		Date of inspection : 25-26 July 2023	
		Report No :	Page 4 of 5

No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remarks and Recommendation
	- Webbing Sling ID: LEE 11825P & LEE 11825O - Shurlock Hook ID: LEE 06692 - Sheave Wheel ID: LEE 10083, SLB 14551 - Lubricator Clamp ID: LEE 02336	-	-	-	Change Colour Code Only Last Inspection on June 2023

I hereby certify that on the date(s) mentioned above, the items described in this report were thoroughly examined so far as was accessible and the particulars given above are correct

Name of the person making this report: Wahyudhi  Qualification of Inspector : CI, LGI, ASNT Level II MT&PT Qualification of Inspector: Company Approved	Name of the person authenticating this report: Signature:	Name & address of employer of persons making and authenticating this report: PT. Inspektindo Sinergi Persada Kawasan Industri Sekupang Kav.No. 13 Batam 29428 – Indonesia Tel : +62 778 326103 / 326104 Fax : +62 778 321388 Email : sales@inspektindo.com
--	--	---

PT. Inspektindo Sinergi Persada
 Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel :+62 (0) 778 326103/326104
 Fax :+62 (0) 778 321338
 Email : sales@inspektindo.com
 Website : www.inspektindo.com
Page 4 of 5

Form No.: ISP/REP/092/Rev.01






DAILY INSPECTION REPORT



Name & address of employer for whom the thorough examination was made: SLB Jl.Mulawarman,Km 20. Manggar Balikpapan 76117 East Kalimantan Indonesia	Address of premises at which the examination was made: Muara Badak & Unit 2340 Wireline	Contract No. :	
		Date of inspection : 25-26 July 2023	
		Report No :	Page 5 of 5

No.	Description of item	Acceptance Criteria	Type of Inspection	Finding Result	Remarks and Recommendation
	- 4 Legs Wire Rope Sling ID: LEE 07500, LEE 10969, SLB 19611, LEE 00716 - Lifting Cap ID: LEE 09999 - Fullbody Harness & Lanyard ID: LEE 11648, LEE 11341-1	-	-	-	Change Colour Code Only Last Inspection on June 2023

I hereby certify that on the date(s) mentioned above, the items described in this report were thoroughly examined so far as was accessible and the particulars given above are correct

Name of the person making this report: Wahyudhi  Qualification of Inspector : CI, LGI, ASNT Level II MT&PT Qualification of Inspector: Company Approved	Name of the person authenticating this report: Signature:	Name & address of employer of persons making and authenticating this report: PT. Inspektindo Sinergi Persada Kawasan Industri Sekupang Kav.No. 13 Batam 29428 – Indonesia Tel : +62 778 326103 / 326104 Fax : +62 778 321388 Email : sales@inspektindo.com
--	--	---

PT. Inspektindo Sinergi Persada
 Komplek Kawasan Industri Sekupang
 Kav. No.13, Batam 29428, Indonesia
 Tel :+62 (0) 778 326103/326104
 Fax :+62 (0) 778 321338
 Email : sales@inspektindo.com
 Website : www.inspektindo.com
Page 5 of 5

Form No.: ISP/REP/092/Rev.01

